

with the

Tim Binegar w/ Marco Deuser

original hole

7" Collapsed at 2555' - Hole was deepened at what depth did
they run well? I say 1306' - how did they cut it off
below the collapsed part + if so, why
leave drill pipe + bottom. Hole was
original Hole plugged? estimate unit?
ask if they can get the Drilling
~~report~~ + workover reports

Ken Blackford - Ken Townsend 6-1-12

Masey, Masey 15

Jim Davidson 303-830-4815

Back off at 2492' run wash pipe to get
picture of collapse - 2 7/8" stuck at 2560'

Stuck at 3521'

fish at 3492'

back off 2 7/8" drill pipe at 3522'

Shot off 7" @ 3419'

~~pull out 7" pipe~~

plug at 3392' 125 SX cement

Top of plug at 3142'

drilled to 3245' after cement job.