

SUBMIT IN TRIPPLICATE

Land Office **Santa Fe**

Lease No. **079329**

Unit **San Juan 32-9 Unit**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL

NOTICE OF INTENTION TO CHANGE PLANS

NOTICE OF INTENTION TO TEST WATER SHUT-OFF

NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL

NOTICE OF INTENTION TO SPOT OR ACIDIZE

NOTICE OF INTENTION TO PULL-OUT AFTER LAMING

NOTICE OF INTENTION TO ABANDON WELL (Temporarily) X

SUBSEQUENT REPORT OF WATER SHUT-OFF

SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING

SUBSEQUENT REPORT OF ALTERING CASING

SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR

SUBSEQUENT REPORT OF ABANDONMENT

SUPPLEMENTARY WELL HISTORY

RECEIVED

JUL 3 1963

U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA

May 10, 1963

Well No. **52** is located **790** ft. from ~~XXXX~~ line and **790** ft. from ~~XXXX~~ line of sec. **13**

SW/4 Sec. 13

32N

9W

N.M.P.M.

Blanco Mesa Verde

San Juan

New Mexico

The elevation of the derrick floor above sea level is **6787** ft.

**DETAILS OF WORK**

State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work.

The production of this well has reached an uneconomical status and therefore  
It is intended to temporarily abandon this well in the following manner:

1. Load hole through tubing w/150 bbls. water.
2. Spot 100 sacks cement through tubing across perforations.
3. Pull up 35 joints and wait 6 hours. Go back in and tag cement top w/tubing.
4. Pull tubing and nipple up Xmas tree.

I understand that this plan of work must be approved by the Geological Survey before operation.

Company **El Paso Natural Gas Company**

Address **Box 990**

**Farmington, New Mexico**

By

**Petroleum Engineer**

