

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-039-11434

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
E-540-11

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
San Juan 32-5 Unit

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
ENERGEN RESOURCES CORPORATION

8. Well No.
18

3. Address of Operator
2198 Bloomfield Highway, Farmington, NM 87401

9. Pool name or Wildcat
Blanco MV/Basin DK

4. Well Location
Unit Letter B : 990 Feet From The North Line and 1650 Feet From The East Line

Section 16 Township 32N Range 6W NMPM Rio Arriba County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
6087 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Water Shut Off & Lewis Pay Add ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is intended to isolate the water production and Add the Lewis formation as follows:

1. MIRU. TOH with Tubing.
2. Set RBP at 5250'. Swab well in and flow test for water shut-off.
3. If successful, set CIBP at 5250'.
4. Selectively perforate Lewis from 3958-4480'. Huerfanito Bentonite top at 3920'
5. Fracture treat w/ 60Q foam.
6. TIH and clean out to PBD. Land tubing at 5200'. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Vicki Donaghey TITLE Production Assistant DATE 3/29/01

TYPE OR PRINT NAME Vicki Donaghey TELEPHONE NO. 505-325-6800

(This space for State Use)

Original Signed by STATE ENGINEER WARDEN

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APR - 2 2001