

**PHILLIPS PETROLEUM COMPANY**

| <b><u>API #</u></b> | <b><u>PROPERTY NAME</u></b> | <b><u>NUMBER</u></b> | <b><u>LOCATION</u></b> |
|---------------------|-----------------------------|----------------------|------------------------|
| 30-039-21789        | San Juan 29-5 Unit          | 89                   | K-34-29N-05W           |
| 30-039-20355        | San Juan 29-6 Unit          | 101                  | B-36-29N-06W           |
| 30-039-23223        | San Juan 30-5 Unit          | 103                  | M-03-30N-05W           |
| 30-045-11453        | San Juan 32-7 Unit          | 3                    | A-18-32N-07W           |
| 30-045-23682        | San Juan 32-7 Unit          | 29A                  | G-18-32N-07W           |
| 30-045-21321        | San Juan 32-7 Unit          | 43                   | B-21-32N-07W           |
| 30-045-11502        | San Juan 32-7 Unit          | 37                   | L-09-32N-07W           |



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178 Fax (505) 334-6170

GARY E. JOHNSON  
GOVERNOR

JENNIFER A. SALISBURY  
CABINET SECRETARY

June 6, 1997

Phillips Pet Co  
5525 Hwy 64 NBU 3004  
Farmington NM 87401

RE: Inactive Wells

To Whom It May Concern:

Our records indicate that the wells on the attached list are inactive and not in compliance with Rule #201.B.

Please submit plans to bring these wells into compliance within 30 days. Review Rules #202 and #203 for the necessary filing requirements to plug and abandon or temporarily abandon these wells.

Contact this office if you have any questions.

Sincerely,

Johnny Robinson  
Deputy O&G Inspector

JR/sh

attachment

XC: TA File JDR File Well Files