

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65
Navajo Tribal

5a. Indicate Type of Lease	State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 14-20-0603-7116		

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Chevron Oil Company, Western Division	8. Farm or Lease Name Navajo Tribal 21
3. Address of Operator P.O. Box 599, Denver, Colorado 80201	9. Well No. 1
4. Location of Well UNIT LETTER F 1980 FEET FROM THE N LINE AND 1980 FEET FROM THE W LINE, SECTION 35 TOWNSHIP 31 N RANGE 18 W NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) DF 5026	12. County San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS	<input type="checkbox"/>	OTHER	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged and abandoned in the following manner:

- 2-3-66 Move in abandonment tools
- 2-4-66 Mix and spot 50 sx plug across perf. 6672-6772
Attempt to squeeze- no press.
- 2-5-66 Test plug- no press.
- 2-7-66 Made 4 dump bailer runs. Spotted 8 sx cement across perf.
- 2-8-66 Check run w/bailer, indicated no fill up.
Dump 55 gal. (Pea gravel and sand in well)
- 2-9-66 Dump 12 sx cement w/dump bailer- 6697 to 6612
- 2-10-66 Load hole w/11#/gel mud and press. test to 1000 psi.
- 2-20-66 Cut 5 1/2" casing off at 3766'- recovered same.
- 2-28-66 Killed water flow w/more mud through tubing from 3050', spotted 35 sx
3050-2950.
Spotted 75 sx plug 2350 to 2550
Spotted 35 sx plug 1150 to 1250
- 3-1-66 Weld plate over surf. casing, install P & A marker



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED O/S T. A. Dugan TITLE Agent DATE 11-1-66

APPROVED BY E. M. Kipp TITLE Manager - Production DATE 4-24-67

CONDITIONS OF APPROVAL, IF ANY: Every 6 months Sup. PRT 111 5-4-67