

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. 14-20-0603-7116
2. NAME OF OPERATOR Standard Oil Company of Texas A Division of Chevron Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo Tribal
3. ADDRESS OF OPERATOR 3610 Avenue E - Bayler, Texas		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit 1; 1900 FRL and 660 FRL of Section 36, T-11N, R-18W		8. FARM OR LEASE NAME Navajo Tribal 21-36
14. PERMIT NO.		9. WELL NO. 2
15. ELEVATIONS (Show whether DF, RT, GR, etc.) DF 5130		10. FIELD AND POOL, OR WILDCAT Indesignated
		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec. 36, T-11, R-18
		12. COUNTY OR PARISH San Juan
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Casing Detail

13-7/8" 49' @ 89'. Cemented to surface.
9-5/8" 364 @ 899'. Cemented to surface.
4 1/2" 9.54' at 8121'. Cemented with 450 ans.

Abandonment Procedure

1. Load casing with 11.0 lb/gal mud. Squeeze cement perforations 6943-76'.
2. Determine free point, shut off and pull recoverable 4 1/2" cas. (est. 6000' recoverable).
3. Spot cement plugs 100' thru casing stub, 50' in casing and 50' above casing, 2500-2700', 1300-1400', and 10 casing at surface.
4. Remove wellhead, weld steel plate on 13-3/8" casing, clean up and level location and install abandoned well marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

J. Davidson
J. Davidson

(This space for Federal or State office use)

TITLE

**RECEIVED
NOV 12 1965
OIL CON. COM.
DIST. DIV.**

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

U. S. GEOLOGICAL SURVEY
FARMING

**RECEIVED
NOV 10 1965
NOV 9, 1965**

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; and other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1964 O-685229

847-881

