

6 BLM 1 C.M. Paul 1 File
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
Federal LS. #NM-10172
C.A. #14-08-0001-7817

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☐ GAS ☒ OTHER ☐

2. NAME OF OPERATOR

C.M. Paul

3. ADDRESS OF OPERATOR

P O Box 208, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1450' FNL - 1450' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, CR, CASE AREA)

5815' RKB

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Elliott

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 20 T31N R13W NMPM

12. COUNTY OR PARISH 13. STATE

San Juan

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Request permission to P & A the subject well as follows:

1. Spot bottom cement plug in 5 1/2" casing from 6650' (PBTD) to 6500' across Dakota formation (20 cf).

2. Spot 100' cement plug in 5 1/2" casing from ⁴⁸⁶⁵5630' to ⁴⁹⁸⁵5730' (13 cf).

3. Spot 100' cement plug from ³³⁷⁶3460' to ³³⁷⁶3560' (13 cf).

4. Spot 100' cement plug in 5 1/2" casing from ¹⁸²⁰1820' to ¹⁷²⁰1920' (13 cf). ^{index} ^{cur} 1550-1450 no cement (F.)

5. Spot 100' cement across 8-5/8" casing shoe from ³⁶⁸240' to ³⁶⁸340' (13 cf).

6. Spot 100' cement plug to surface (13 cf).

7. Plan to install permanent dry hole monument.

8. Plan to fill all pits.

9. Plan to clean well location of all equipment, pipe, junk and trash.

10. Plan to restore surface.

11. Plan to cut off tie-downs.

Note: We do not plan to pull casing.

18. I hereby certify that the foregoing is true and correct

SIGNED

Sherman E. Dugan

TITLE Geologist

DATE 3-5-87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE MAR 11 1987

CONDITIONS OF APPROVAL, IF ANY:

AREA MANAGER

*See Instructions on Reverse Side

NMOC

and willfully to make to any department or agency of the

