,	UNITED STATES RTMENT OF THE INTERIO REAU OF LAND MANAGEMENT	SUBMIT IN TRIPLICATES (Other instructions on reverse side)	Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEARS DESIGNATION AND SERIAL NO. 14-20-604-1939
SUNDRY N	OTICES AND REPORTS ON Opposals to drill or to deepen or plus been LICATION FOR PERMIT—" for such proper	WELLS	0. IF INDIAN, ALLOTTEE OR TRIBE NAME Ute Mountain Tribal
OIL GAS OTER		NOV 07 1985	7. UNIT AGESSMENT NAME
	er Drilling Corp.		Ute Mountain Tribal 1939.
3. ADDRESS OF OFERATOR DUTANGO, Colorado 221 Petroleum Center Building, Farmington, New Mexico			9. WELL NO.
4. LOCATION OF WELL (Report locati See also space 17 below.) At surface	on clearly and in accordance with any Sta	te requirements. 87401	#10 / 10. FIBLD AND FOOL, OR WILDCAT Verde Gallup /
OOO! PNI 660! PI	L, Sec. 29, T31N, R1	117.7	11. SEC., T., E., M., OR BLE. AND SURVEY OR AREA
			Sec. 29, T31N, R14W /
14. PERMIT NO.	16. BLEVATIONS (Show whether DF, RT, 5623 GR	GR, etc.)	San Juan New Mexico
TEST WIRE SHOT-OFF PULL ON AUTER CASING WATER SHOT-OFF SEPARING WALL SHOOT OR ACIDISM SHOOT			
Cement plug #2 - Cemented through perforations at 1206-1207' with 45 cubic feet cement slurry. Plug failed, ran in hole with tubing and did not find cement. Cement plug #3 - Cemented through perforations at 1206-1207' with 45 cubic feet			
cement slurry. Cement plug located at 887' by running in hole with tubing. Shot off 5-1/2" casing at 847'.			
Cement plug #4 - Cemented 194' to surface with 71 cubic feet cement slurry.			
Set and cemented dry hole marker. Cleaned up location. Well permanently plugged / and abandoned.			
18. I hereby certify that the foregoing	If true and corress		
SIGNET SULP DE	TITLE VIC	e President	DATE 11/06/85
(This space for P			
APPROVED BY Sally W	sely AREA	MANAGER	
ABANDONMENT OF THE WEL SURFACE RESTORATION AR	111000		,
THE OPERATOR'S LIABILI	TY FOR THE Instructions on	Reverse Sid	
WELL IS HEREBY RELEASE	D. person knowing: ints or represen		