5. LEASE

14-08-0001-8200

# UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY  6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
	Navaje Ute Mtn.	<del></del>	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME Horseshoe Gallup Unit		
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAM		
1. oil gas	Horseshoe Gal.	lup Unit	
well well other Injection	9. WELL NO.		
2. NAME OF OPERATOR ARCO Oil and Gas Co., a	145 10. FIELD OR WILDCAT N	IAME	
Div. of Atlantic Richfield Company  3. ADDRESS OF OPERATOR 707 - 17th Street,			
P.O. Box 5540, Denver, Colo. 80217	Horseshoe Gallup  11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA		
below.)	Sec. 21-31N-16W		
AT SURFACE: Unit 0,820'FSL & 1820'FEL, Sec. 21	12. COUNTY OR PARISH		
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan	New Mexico	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. None		
		DF. KDB. AND WD)	
	1. 55 GEDENGTON SURVEY DIL AND BAS OFERATIONS	51, 1152, 1116 NG,	
	ULULINEU EVALIONS		
TEST WATER SHUT-OFF U U FRACTURE TREAT   GRACTURE TREAT	SEP 23 1982		
SHOOT OR ACIDIZE	JLF 23 1302		
REPAIR WELL	(NOTE: Report results of m change on Form 9-		
PULL OR ALTER CASING  MULTIPLE COMPLETE  GR	AND JUNCTION, COLORADO	-330.,	
CHANGE ZONES	SONOTION, COLUMNIO		
ABANDON* (other) X - Set Cement Plug			
th.			
17. DESCRIBE PROPOSED OR COMPLETED OF TRATIONS (Clearly stating including estimated date of starting any proposed work. If well is constant to the starting and proposed work.	le all pertinent détails, and	give pertinent dates,	
measured and true vertical depths for all markers and zones pertine	nt to this work.)*		
ARCO hereby asks permission to set a ce	ment plug above	the injection	
	t well. This is		
with the requirements as set forth in a	memorandum dat	ed September 30	
1981, and a subsequent letter of April			
of New Mexico, Energy and Minerals Depa	rtment, Oil Con	servation	
Division(copies attached.)			
Attached is the procedure for setting	he cement plug.		
	<b>N</b>	e i M G IO	
√	oc l	1 6 1982	
SEP 3 0 198	JLI JLI	1 0 1302	
Subsurface Safety Valve: Manuand Type	MINERALS MA	NAGEMENT SET Ft.	
TION -	DUR	ANGO, CO	
18. I hereby certify that the foregoing is true and correct		+ 21 1002	
S. C. / ROSE	Supt.DATE Augus	t 31, 1982	
APPROVED BY THE SIGNED STATE STATE SUPPONIES SPACE FOR FEDERAL SUPPONIES STATE SUPPONIES SUPPONI	ffice use)	. 1002	
APPROVED BY THE SIGNED SEPTEMBELLE TITLE DISTRICT SUPERVI	SOT DATE SEP 2	4 1982	
CONDITIONS WHILE BAYES THE ANT	<del></del>		

## HORSESHOE GALLUP UNIT INJECTION WELLS

## PLUGGING PROCEDURE

- 1. MIRU.
- 2. Release packer and pull tubing and packer out of hole.
- 3. RIH with tubing open-ended to 40' above the top perforation and pump sufficient cement to set a 100' plug inside the casing (Using light-weight cement).
- 4. POH, RD, and move off.





#### STATE OF NEW MEXICO

## ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

BRUCE KING SOVERNOR ARRY KEHOE

April 26, 1982

POST OFFICE BOX 2088 STATE LAND OFFICE BUILDING SANTA FE. NEW MEXICO 87501 (505) 827-2434

ցեթ **3 0 1982** 

DIST. 3

JUN. COM.

RECEIVED

APR 30 1982

ENGINEERING

Arco Oil & Gas Company P.O. Box 5540 Denver, Colorado 80217

ATTENTION: J. G. Bradshaw

RE: Exception to Rule 705-A for Injection Wells in the Horseshoe Gallup Unit, Federal Lease No. 14-08-0001-8200, San Juan County, New Mexico.

Dear Sir:

Pursuant to your letter of February 18, 1982, requesting exception to Rule 705-A for fifty-seven (57) wells as listed on Table I, the Oil Conservation Division hereby denies both of your requests. You are hereby requested to take prompt action as outlined in the September 30, 1981, Memorandum. (Copy enclosed).

The Oil Conservation Division will not grant an exception to Rule 705-A if a well will not be placed in service within 6 months of the request. For future reference, supportive data for exception to Rule 705-A should include:

- 1. Proof of mechanical integrity, such as bradenhead tests, tracer logs, or other supportive tests or data.
- 2. All related OCD Division Order Numbers or Case Hearing Numbers.
- 3. A schematic of the present injection well including cement tops and quantities thereof.
- 4. Date each well was shut-in.

If you have any questions regarding this matter, please do not hesitate to contact me at (505) 827-2533.

Sancerely,

JOE D. RAMEY

Division Director

## TABLE I

Horeshoe Gallup Unit Federal Lease No. 14-08-001-8200 San Juan County, New Mexico.

## List of Wells

1.	No.	26 £	3	
2.	No.	29	3	
3.	No.	103	A	
4.	No.	105	A	
5.	No.	113	A	
6.	No.	126	C	
7.	No.	130	C	
8.	No.	132	C	
9.	No.	135	C	
10.	No.	137	C	
11.	No.	139	Ç	
12.	No.	141	C	
13.	No.	143	D	
14.	No.	145	$\mathcal{D}$	
15.	No.	148	$\mathcal{D}$	
16.	No.	150	D	
17.	No.	152	$\mathcal{D}$	
18.	No.	154	D	
19.	No.	156	D	
<del>-20.</del>	No.	160	<u> </u>	

21.	No.	215	D
22.	No.	162	0
23.	No.	164	D
24.	No.	<del>169</del>	<del>-D-</del>
25.	No.	171	D
26.	No.	173	D
27.	No.	175	D
-28.	No.	180-	<del>-</del>
29.	No.	182	D
30.	No.	184	O
31.	No.	186	۵
-32	No.	192	<del>D</del>
33.	No.	194	D.
34.	No.	196	D
-35	-No.	201	9
36.	No.	203	D
37.	No.	205	D
38.	No.	207	D
39.	No.	213	Q
40.	No.	217	D

41.	No.	223	P
42.	No.	225	D
43.	No.	227	D
44.	No.	229	D
45.	No.	238	D
46.	No.	240	D
47.	No.	248	D
48.	No.	250	D
49.	No.	259	D
50.	No.	261	C
51.	No.	263	C
52.	No.	269	С
53.	No.	274	C
54.	No.	275	C
55.	No.	73	Ą
-56.	No.	199	D
<del>-57 .</del>	No.	-211	<del>D</del>
	OM,	٠.,.	



## ENERGY AND IVITINEMALD DEPARTIVIEW I

POST OFFICE BOX 20 STATE LAND OFFICE BL . SANTA FE. NEW MEXICO : (505) 827-2434

BRUCE KING SOVERNOR LARRY KEHOE -SECRETARY

MEMORANDUM

TO:

ALL NEW MEXICO INJECTION WELL OPERATORS

FROM:

JOE D. RAMEY, DIRECTOR

SUBJECT:

TEMPORARY ABANDONMENT OF INJECTION WELLS

Division Rule 705A provides in part that "no injection well may be temporarily abandoned for more than six months unless the injection interval has been isolated by use of cement or a bridge plug." The Division Director may delay the cement or bridge plug requirement upon a request by the operator and a showing that such well is mechanically sound, that there is a continuing need for the well, and that the well constitutes no threat to underground sources of drinking water.

Division survey programs have found several hundred injection wells which have not been used for at least six months and which do not have the requisite plugs. Based upon these surveys the Division will be moving to enforce Rule 705A in the near future.

Operators should review the status of their injection wells and within the next six months take one of the following actions relative to injection wells which have been shut in for six months or longer:

- (1) Return the well to active operation.
- (2) Plug and abandon the well or place a <u>cement</u> or bridge plug above the injection interval.
- (3) File a workover or plugging plan and schedule with the appropriate Division district office.
- (4) File a request for exception to Rule 705A with the Division Director in Santa Fe.

September 30, 1981 fd/

## CONDITIONS FOR APPROVAL

- 1. Plug to be tagged or pressure tested to 1000 psi.
- 2. Casing at the surface shall be secured with a valve or cap.
- 3. Approval effective for one year only.