UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	14-20-604-1951
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Ute_Mountain
SUNDRY NOTICES AND REPORTS ON WELLS	7 UNIT AGREEMENT NAME
Do not use this form for proposals to drill or to deepen or plug back to a different isservoir. Use Form 9-331-C for such proposals.)	Horseshoe Gallup Unit
servoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil — gas —	Horseshoe Gallup Unit
well — well — other X - Injection	9. WELL NO.
2. NAME OF OPERATOR ARCO Oil & Gas Co., Div. of	164
Atlantic Richfield Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR 707-17th Street,	Horseshoe Gallup Unit
P.O. Box 5540, Denver, CO 80217	11. SEC., T., R., M., OR BLK. AND SURVEY CR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	AREA Sec. 27-31N-16W
below.) Unit "J"	
AT SURFACE: 1980' FSL & 2080' FEL, Sec. 27	12. COUNTY OR PARISH- 13. STATE
AT TOP PROD. INTERVAL: Appx. same	San Juan New Mexico
AT TOTAL DEPTH: Appx. same	14. API NO.
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	None Assigned
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5477 GR
	of the control of
TEST WATER SHUT-OFF THE TRACTURE TREAT	
SHOOT OR ACIDIZE	
HOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE TOTAL CONTROL TOTAL TOTAL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	Change on Fores 3-350.7
AULTIPLE COMPLETE =	
ABANDON.	
other)	•
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	irectionally drilled, give subsurface locations and
ARCO has plugged and abandoned the subject wel	
Notice dated December 30, 1982, and approved b	
	Gallup fm. Spotted cement plugs
as per the attached plugging operations report	

Completed P & A, 7-13-83.

Final restoration will be commenced as soon as weather permits. An additional subsequent report will be filed when restoration has been completed.

APPROVED TO THE PLUGGING OF THE WELL BORE ONLY. LIABILITY UNDER THE BOND RETAINED UNTIL SURFACE RESTORATION IS COMPLETED AND ŧ. Subsurface Safety Valve: Manu. and Type _ - APPROVED. 18. I hereby certify that the foregoing is true and correct TITLE Dist.Prod. Supt. DATE November 30, 1983 Rose (This space for Federal or State office use) L. Mark Holls Miller : TITLE ACTING DATE APPROVED BY CONDITIONS OF APPROVAL IF ANY AREA MANAGER

HSG #164 Horseshoe Gallup Field

P & A OPERATIONS:

MI RU 7/11/83. Rel'd pkr & POH w/pkr & tbg. RIH w/OE tbg. Spt 15 sx neat cmt. Pull 15 jts. Sqz cmt into Gallup. WDC. SDFN.

Perf 4 shots @ 1248'. Spt 28 sx neat cmt. Sqz 18 sx thru perfs w/500 psi. WOC. Perf 2 shots @ 168'. Spt 30 sx. Sqz cmt thru perfs. WOC. RD & MO 7/12/83. SDON.

FINAL REPORT - WELL P & A, 7/13/83.

CONDITIONS OF APPROVAL AND ADDITIONAL REQUIREMENTS

- 1. This Subsequent Report of Abandonment (SRA) is approved to the plugging of the well bore only. Liability under the bond is retained until surface restoration is completed and approved.
- 2. Once the dirt work has been completed, the operator will submit Form 3160-5, Sundry Notice, informing the Bureau of Land Management (BLM) of this operation. This Sundry Notice, or Second Subsequent Report of Abandonment (SSRA) will be an acceptance rather than an approval action. (Instruction Memorandum No. CO-87-417).
- 3. Form 3160-5, Sundry Notice, will be submitted when all restoration is completed. This Sundry Notice, or Final Abandonment Notice (FAN), will be submitted only when the site is ready for inspection by an official of the BLM.
- 4. PHASED RELEASE OF BOND LIABILITY After proper plugging of the leasehold's well(s), and after the site has been stabilized and seeded, a percentage of the bond liability can be released. Operators who wish to request partial liability release of a single lease bond may delay filing Form 3160-5, Second Subsequent Report of Abandonment (SSRA) until after the site has been reseeded. In this case, the Sundry Notice should not only detail work that was done but also request partial bond liability release. (Instruction Memorandum No. CO-87-307).