EASE 14-20-604-1951 14-08-0001-8200

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY


	Marojo - Ute Mtn.	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME Horseshoe Gallup Unit	
The not use this form for proposals to drill or to deepen or plug back to a different		
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME Horseshoe Gallup Unit	
1. oil gas other Injection	9. WELL NO.	
2. NAME OF OPERATOR ARCO Oil and Gas Co., a	156	
Div. of Atlantic Richfield Company	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR 707 - 17th Street,	Horseshoe Gallup	
P.O. Box 5540, Denver, Colo. 80217	11. SEC., T., R., M., OR BLK. AND SURVEY OR	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA	
helow)	Sec. 27-31N-16W	
AT SURFACE: Unit F, 1900' FNL & 2050' FWL, Sec. 27	12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL:	San Juan New Mexico	
AT TOTAL DEPTH:	14. API NO	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	None	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5767'GR	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5767' GR GFOLOGICAL SURVEY	
TEST WATER SHUT-OFF	OIL AND GAS OPERATIONS	
FRACTURE TREAT		
SHOOT OR ACIDIZE	(NOTE: Report results a noutral Completion or zone	
PULL OR ALTER CASING	change on Form 9-330.)	
MULTIPLE COMPLETE		
CHANGE ZONES	GRAND JUNCTION, COLORADO	
ABANDON* (other) X - Set Cement Plug	The serverson, columning	
(other) A - Bet Cement Flug	in the second se	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertined	firectionally drilled, give subsurface locations and	
with the requirements as set forth in a 1981, and a subsequent letter of April of New Mexico, Energy and Minerals Depa Division (copies attached.)	t well. This is in compliance memorandum dated September 30 26, 1982, both from the State	
Attached is the procedure for setting at	1	
SEP 3	OAD82 REGEIVED	
	SEP 1 6 1982	
A CONTRACTOR OF THE CONTRACTOR		
Subsurface Safety Valve: Manu. and Type	MINERALS MANAGEMENT SET Ft.	
18. I hereby certify that the foregoing is true and correct		
SIGNED Stephen Kose TITLE Dist. Prod.		
Original Signed - Scott L. Ellis APPROVED BY APPROVED B	RICE	
CONDITIONS OF APPROVAL IF ANY: District Supe	37450F DATE - 321 2 4 1982	

ATTACHED

HORSESHOE GALLUP UNIT INJECTION WELLS

PLUGGING PROCEDURE

- 1. MIRU.
- 2. Release packer and pull tubing and packer out of hole.
- 3. RIH with tubing open-ended to 40' above the top perforation and pump sufficient cement to set a 100' plug inside the casing (Using light-weight cement).
- 4. POH, RD, and move off.





STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

ARRY KEHOE

April 26, 1982

POST OFFICE BOX 2088
STATE LAND OFFICE BUILDING
SANTA FE, NEW MEXICO 87501
(505) 827-2434

Arco Oil & Gas Company P.O. Box 5540 Denver, Colorado 80217

ATTENTION: J. G. Bradshaw

RECEIVED
APR 3 0 1982
ENGINEERING

RE: Exception to Rule 705-A for Injection Wells in the Horseshoe Gallup Unit, Federal Lease No. 14-08-0001-8200, San Juan County, New Mexico.

Dear Sir:

Pursuant to your letter of February 18, 1982, requesting exception to Rule 705-A for fifty-seven (57) wells as listed on Table I, the Oil Conservation Division hereby denies both of your requests. You are hereby requested to take prompt action as outlined in the September 30, 1981, Memorandum. (Copy enclosed).

The Oil Conservation Division will not grant an exception to Rule 705-A if a well will not be placed in service within 6 months of the request. For future reference, supportive data for exception to Rule 705-A should include:

- 1. Proof of mechanical integrity, such as bradenhead tests, tracer logs, or other supportive tests or data.
- 2. All related OCD Division Order Numbers or Case Hearing Numbers.
- 3. A schematic of the present injection well including cement tops and quantities thereof.
- 4. Date each well was shut-in.

If you have any questions regarding this matter, please do not hesitate to contact me at (505) 827-2533.

Sancerely,

JOE D. RAMEY

Division Director

TABLE I

Horeshoe Gallup Unit Federal Lease No. 14-08-001-8200 San Juan County, New Mexico.

List of Wells

1.	No.	26	В
----	-----	----	---

- 2. No. 29 B
- 3. No. 103 A
- 4. No. 105 A
- 5. No. 113 A
- 6. No. 126 C
- 7. No. 130 C
- 8. No. 132 C
- 9. No. 135 C
- 10. No. 137 C
- 11. No. 139 C
- 12. No. 141 C
- 13. No. 143 D
- 14. No. 145 D
- 15. No. 148 D
- 16. No. 150 D
- 17. No. 152 D
- 18. No. 154 D
- 19. No. 156 D
- 20. No. 160 D

- 21. No. 215 D
- 22. No. 162
- 23. No. 164 D
- 24. No. 169
- 25. No. 171 D
- 26. No. 173
- 27. No. 175 D
- 28. No. 180
- 29. No. 182 D
- 30. No. 184 D
- 31. No. 186
- -32. No. 192
- 33. No. 194 D
- 34. No. 196 D
- 35. No. 201
- 36. No. 203 D
- 37. No. 205 D
- 38. No. 207 🕀
- 39. No. 213 📮
- 40. No. 217 D

- 41. No. 223 D
- 42. No. 225
- 43. No. 227 D
- 44. No. 229 D
- 45. No. 238 D
- 46. No. 240 D
- 47. No. 248 D
- 48. No. 250 D
- 49. No. 259 D
- 50. No. 261 C
- 51. No. 263 C
- 52. No. 269 C
- 53. No. 274 C
- 54. No. 275 C
- 55. No. 73 A
-

56. No. 199

57. No. 211 F

SEP 3 0 1982 OIL CUN. COM. DIST. 3



ENERGY AND IVIINERALS DEPARTIVIENT OIL CONSERVATION DIVISION

POST OFFICE BOX 20 STATE LAND OFFICE BU : SANTA FE, NEW MEXICO : (505) 827-2434

BRUCE KING SOVERNOR LARRY KEHOE -

MEMORANDUM

TO:

ALL NEW MEXICO INJECTION WELL OPERATORS

FROM:

JOE D. RAMEY, DIRECTOR

SUBJECT:

TEMPORARY ABANDONMENT OF INJECTION WELLS

Division Rule 705A provides in part that "no injection well may be temporarily abandoned for more than six months unless the injection interval has been isolated by use of cement or a bridge plug." The Division Director may delay the cement or bridge plug requirement upon a request by the operator and a showing that such well is mechanically sound, that there is a continuing need for the well, and that the well constitutes no threat to underground sources of drinking water.

Division survey programs have found several hundred injection wells which have not been used for at least six months and which do not have the requisite plugs. Based upon these surveys the Division will be moving to enforce Rule 705A in the near future.

Operators should review the status of their injection wells and within the next six months take one of the following actions relative to injection wells which have been shut in for six months or longer:

- (1) Return the well to active operation.
- (2) Plug and abandon the well or place a <u>cement</u> or bridge plug above the injection interval.
- (3) File a workover or plugging plan and schedule with the appropriate Division district office.
- (4) File a request for exception to Rule 705A with the Division Director in Santa Fe.

September 30, 1981 fd/



COMPATIONS FOR AMERICAL

- . Fing this campai or pressure to red to 1980 ost.
- 2. Ossing as the purface shall be secured with a make on cope
- 3. Approval office live for one year oly