

8 5/8 @
127'

LEASE Mudge LS

WELL NO. 42

CASING:

8 5/8 "OD, 24 LB, K5 CSG/W 107 Cu Ft

TOC @ surf. HOLE SIZE 12 1/4 DT: 11/3/72

REMARKS _____

2 7/8 "OD, 6.4 LB, J5 CSG/W 551 Cu Ft

TOC @ 1050. HOLE SIZE 6 3/4 DT: _____

REMARKS _____

_____ "OD, _____ LB, _____ CSG.W/ _____ SX

TOC @ _____. HOLE SIZE _____ DATE _____

REMARKS _____

TUBING:

1 1/4 "OD, 2.33 LB, K-55 GRADE, 10 RD, IJ CPLG

LANDED @ 2629. SN, PACKER, ETC. Mod C-1 @ 2496'.

_____ "OD, _____ LB, _____ GRADE, _____ RD, _____ CPLG

LANDED @ _____. SN, PACKER, ETC. _____

PUMP _____ RODS _____ ANCHOR _____

DETAILED PROCEDURE:

1. Blow dn well. Kill tbg. Release pkr & POOH. (Note: pkr set in compression)
2. RIH w/ tbg and pkr. Set pkr @ 2400'.
3. CMT PC perms w/25 sx CL B. Displace cmt to 2500'. Release pkr and POOH. Laying dn tbg. Release rig.
- * 4. Tie onto 2-7/8" csg. Open 2-7/8" x 8-5/8" bradenhead. Cmt 2-7/8 and annulus w/100 sx CL B (Note: casing leak at $\pm$ 1000 ft.)
- * 5. Weld on P&A marker showing well name, location, date, lease #078040.
6. Clean and restore location.
1598

* See attached

2588-2608

2622-32

2 7/8 @

2728

2 7/8 - .006 BBL/ft.

2 7/8 x 6 3/4 - .0362 BBL/ft.

4.75 SK/BBL