Form 3160-5 (June 1990)

representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR


FORM APPROVED Budget Bureau No. 1004-0135

BUREAU OF LAND MANAGEMENT	Expires: March 31, 1993	
CUMPRY MOTICES AND DEPORTS ON WELLS	6. Lease Designation and Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS	SF-078097	
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals	6. If Indian, Allottee or Tribe Name	
	7. If Unit or CA, Agreement Designation	
1. Type of Well Oil Gas Well Ges Other	8. Well Name and No.	
2. Name of Operator Attention:	Heaton M/LS 29	
Amoco Production Company Dallas Kalahar	9. API Well No.	
3. Address and Telephone No.	3004521113	
P.O. Box 800, Denver, Colorado 80201 (303) 830-5129	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	AZTEC Pict- Cliffs	
1850' FSL 800' FEL Sec. 29 T 31N R 11W	11. County or Parish, State	
1850' FSL 800' FEL Sec. 29 T 31N R 11W	Son Juan Now Maying	
	San Juan , New Mexico	
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA	
TYPE OF SUBMISSION TYPE OF ACTION		
NZI		
Notice of Intent	Change of Plans	
Plugging Back	New Construction Non-Routine Fracturing	
Subsequent Report Casing Repair	Water Shut-Off	
Altering Casing	Conversion to Injection	
Final Abandonment Notice	Dispose Water	
	rt results of multiple completion on Well Completion or on Report and Log form.)	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting	any proposed work . If well is directionally drilled, give	
subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work,)*		
AMOCO PRODUCTION COMPANY intends to Plug and Abandon the subject well.		
	8375	
See attached for procedures.	8 V 5	
The state of the s		
NOV1 0	1993	
If you have any questions, please contact Dallas Kalahar at 303-830-5129. OIL CON. DIV.		
DIST		
	•	
	· · · · · · · · · · · · · · · · · · ·	
	51% - 613 - 12	
SEE ATTACHED FOR	\mathbb{Z} \mathbb{Z}	
CONDITIONS OF APPROVAL		
<u> </u>		
14. I hereby certify that the oregaing is true and correct		
Signed Staff Business A	Analyst Date 10-25-1993	
(This space for Federal or State office use)	APPROVED	
Approved by Title	A-F-+	
Conditions of approval, if any:	NOV 0 8 1993	
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States representations as to any matter within its jurisdiction.	A MACED	

PXA Procedures Heaton LS #29

- 1. Blow down well. Kill if necessary with fresh water.
- 2. RU wireline. Set cement retainer at 2300'. Test casing integrity to 500#. If okay RU cementer and pump truck. Establish injection rate through perfs at 2352' to 2404'. Spot cement plug to 540'. (estimate 35.976 cuft cement)
- 3. If not MIRUSU. RIH with tbg and squeeze perfs at 2352' to 2404. (19.44cuft) Pull out of retainer and spot cement plug to 2000'. (84.15 cuft cement) Isolate leak in casing, contact BLM, and see if further procedures are needed.
- 4. RIH with perforating gun and shot squeeze holes at 500'. Attempt to circulate to surface through squeeze holes and displace cement to surface. (191.343 cuft cement)
- 5. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Turn well over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

HEATON LS 029 Location — 311—31N—11W SINGLE PC Orig.Completion — 12/72 LAST FILE UPDATE 9/93 BY CSW



UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 La Plata Highway Farmington, New Mexico 87401

A •		^
Attachment	to Note	ra nt
$\Delta uacunucu$	LLJ LYLJEL	

Re: Permanent Abandonment

Intention to Abandon

Well: 29 Heaton LS

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
- 2. Mike Flaniken with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made (when applicable):

Recalulate cement volumes in procedure.

At a minimum!

1.) Place a cement pluy from 2404' to 1936' plus 50' excessinside the cusing.

2.) Place a cement pluy from 941' to E19' inside the casing plus 50' excess.

3.) Perforate the casing 2 183' and circulate cement to the surface.

Office Hours: 7:45 a.m. to 4:30 p.m.