rorm approved. Budget Bureau No. 1004-0135 UNITED STATES

SUBMIT IN TRIPLICATE\*

Other instructions on re
OTHE INTERIOR verse side) Form 3160-5 Expires August 31, 1985 (November 1983) 5. LEASE DESIGNATION AND SERIAL NO. (Formerl: 9-231) 14--20--603--2034 BUREAU OF LAND MANAGEMENT 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT" for such proposals.) Navajo Tribal 7. UNIT AGREEMENT NAME WELL X GAS WELL OTHER S. FARM OR LEASE NAME 2. NAME OF OPERATOR Navajo Tribe of Indians 'F' Marmac Petroleum Co. 9. WBLL NO. 3. ADDRESS OF OPERATOR LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)

At surface 145 10. FIELD AND POOL, OR WILDCAT <u>Horseshoe Gallup</u> 11. SHC., T., B., M., OR BLK. AND SURVEY OR AREA 10--31N--17W 660' FSL & 1980' FWL 12. COUNTY OR PARISH 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. San Juan NM 5190' GR 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data SUBSEQUENT EMPORT OF: NOTICE OF INTENTION TO: REPAIRING WELL TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING FRACTURE TREAT SHOOTING OR ACIDIZING ARANDON MENT® ABANDON\* RHOOT OR ACIDIZE (Other) Temporarily Abandon CHANGE PLANS REPAIR WELL (Nors: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) Since we have just become operatoron the above lease, we have not had proper time to evaluate if we wish to permanently abandon the above well therefor we would like to temporarily abandon with the following procedure. Surf cgs 7" @ 68' KB Prod cgs 4 1/2' @ 898 KB Perfs 817 -- 839 TD 903 Procedure MI service Rig RIH w/ tbg, Displace 25 sx cement 10' above perfs Pull tubing to top of cement Displace hole with 9.2# mud to surface Pull tbg to 150 +. Keep hole full w/ mud Displace 25 sx cement to surface Pull tbg LD tbg Clean up location, Move to next location

THIS APPROVAL EXPINES

IR. I hereby certify that the foregoing is suit and correct

SIGNED TITLE Production Supervisor

(This space for Federal of State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

NMOCC FARMING. Churandham.

\*See Instructions on Reverse Side