14. PERMIT NO.

16.

## **UNITED STATES** SUBMIT IN TRIPLICATE. DEPARTMENT OF THE INTERIOR (Other Instructions on re-

١			Form Budge	a et	pprov Bure	ed. au N	<b>6</b> .	′ 42–R	1424
Γ	5.	LEASE	DESIG	N	ATION	AND	SI	RIAL	NO.

12. COUNTY OR PARISH 13. STATE

San Juan

New Mexico

GEOLOGICAL SURVEY	SF-080313   /
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS WE'L WELL OTHER	7. UNIT AGREEMENT NAME
NAME OF OPERATOR	8. FARM OR LEASE NAME
Southland Royalty Company	Harrison
ADDRESS OF OPERATOR	9. WELL NO.
P.O. Box 570, Farmington, New Mexico 87401	#1-A
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	Blanco Pictured Cliffs Blanco Mesa Verde
810' FNL & 895' FWL	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
	Section 31, T32N, R10W

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

6170' GR

15. ELEVATIONS (Show whether DF, Rr. CR, etc.)

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE		PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON*	<u>X</u>		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING	REPAIRING WELL ALTERING CASING ABANDONMENT*	
REPAIR WELL (Other)		CHANGE PLANS			(Other)  (Note: Report results of m Completion or Recompletion	ultiple completion on Well Report and Log form.)	] l

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*
  - Pull 1 1/2" tubing. 1.
  - Set Baker model "F" packer with knock out plug @ 3100'.
  - Perforate Pictured Cliffs from 2972' to 3019' with 7 holes.
  - Frac Pictured Cliffs with 65,000 gallons of water and 63,000# of 20/40 sand.
  - Clean out with air to packer and knock out expendable plug. 5.
  - Land 1 1/2" tubing @ 5238' with seal assembly in packer @ 3100'
  - Land 1 1/4" tubing @ 2950'.
  - Nipple up qual wellhead.



1	8. I hereby certify that the foregoing is true and correct SIGNED An Man	TITLE District Production Manager	DATE	9-7-78	
==	(This space for Federal or State office (2)				
	APPROVED BY	TITLE	DATE		

\*See Instructions on Reverse Side

kde