

OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO 1000 RIO BRAZOS RD. - AZTEC

87410

LAND COMMISSIONER
PHIL R. LUCERO

STATE GEOLOGIST

STATE GEOLOGIST EMERY C. ARNOLD

DIRECTOR
JOE D. RAMEY

April 13, 1976

Mr. W. K. Arbuckle Kimbark Operating Company Suite 808 1860 Lincoln Street Denver, Colorado 80203

Re: Kimbark Operating Company, Horton #1A, G-7-31N-11W

Dear Mr. Arbuckle:

The Form 9-330, Well Completion Log, for the subject well shows a packer set at 7272 feet without tubing to the surface.

To produce this well as a Mesaverde single completion will require a cement plug above the packer to separate the two sets of perforations.

To produce this well as a Dakota-Mesaverde dual completion will require tubing through the packer, a packer-leakage test and a multiple completion order.

To produce this well as a down-hole commingled well will require an order to authorize the down-hole commingling after notice and hearing.

The selection of direction is up to the Kimbark Operating Company. I cannot assure you of approval of down-hole commingling after the hearing.

if there are questions, please contact us.

Yours very truly,

A. R. Kendrick

Supervisor, District #3

ARK:mc

cc: Elliott Riggs