UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	buildly livel	ces and Report	S On Werrs		
				5.1	Lease Number NM-0608
Type of Well			A 1773	6.	If Indian, All. or Tribe Name
				آغ . اکار	Unit Agreement Nam San Juan 32-9 Unit
. Name of Opera		00			San odan 3.2-9 onic
RESOU	IGION RCES OTL A	GAS COMPANY			
				8.	Well Name & Number
3. Address & Pho	ne No. of Operat	or	000	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	San Juan 32-9 U#13 API Well No.
PO Box 4289,	Farmington, NM	87499 (505)	326-9700	9.	30-045-22912
1 Togation of V	Well, Footage, Se	C., T, R, M		10	Field and Pool
1190'FSL, 114	10'FEL, Sec.14, T	7-31-N, R-10-W	, NMPM		Blanco Mesaverde
,				11	. County and State
					San Juan Co, NM
	PRIATE BOX TO INI	TCATE NATURE	OF NOTICE,	REPORT, OTHE	R DATA
Type of Submi		T	ype of Actio	on	
	ce of Intent	Abandonm	ent	Change of P	lans
		Recomple	tion	New Constru	ction
X_ Subse	equent Report	Plugging	Back	Non-Routine	Fracturing
		Casing R	epair	Water Shut	oII to Injection
Final	l Abandonment	Altering _X_ Other -	Casing	Conversion	to Injection
		x Other -	Tubing repa		
		- -	-		
13. Describe	Proposed or Comp				
13. Describe	Proposed or Comp				
8-17-00	MIRII SDON.	leted Operatio	ns		int the @ 5800'.
	MIRU. SDON. TOOH w/pump & r	leted Operation ods. ND WH. NUtbg @ 5770'. T	ns BOP. Tbg s	tuck. Freepo	eint tbg @ 5800'. or weekend.
8-17-00 8-18-00 8-21-00	MIRU. SDON. TOOH w/pump & r Chemical cut TIH w/fishing t	ods. ND WH. NUtbg @ 5770'. Tools. Fish for	ns BOP. Tbg s COOH w/2 3/8	tuck. Freepo	eint tbg @ 5800'. or weekend.
8-17-00 8-18-00 8-21-00 8-22-00	MIRU. SDON. TOOH w/pump & re Chemical cut TIH w/fishing t Washover fish t	ods. ND WH. NUtbg @ 5770'. Tools. Fish for o PBTD @ 5881'	ns BOP. Tbg s COOH w/2 3/8 tbg. SDON SDON.	tuck. Freepo	int tbg @ 5800'. or weekend.
8-17-00 8-18-00 8-21-00 8-22-00 8-23-00	MIRU. SDON. TOOH w/pump & re Chemical cut TIH w/fishing t Washover fish t	ods. ND WH. NUtbg @ 5770'. Tools. Fish for PBTD @ 5881'	ns BOP. Tbg s OOH w/2 3/8 tbg. SDON SDON.	tuck. Freepo " tbg. SD fo	r weekend.
8-17-00 8-18-00 8-21-00 8-22-00	MIRU. SDON. TOOH w/pump & re Chemical cut TIH w/fishing t Washover fish t Latch onto fish TIH w/186 jts 2 pump & rods.	ods. ND WH. NU tbg @ 5770'. Tools. Fish for o PBTD @ 5881'. TOOH w/fishi 3/8" 4.7# J-5	ns BOP. Tbg s COOH w/2 3/8 tbg. SDON SDONng tools & 55 tbg, set	tuck. Freepo " tbg. SD fo	oint tbg @ 5800'. or weekend. BOP. NU WH. TIH w/
8-17-00 8-18-00 8-21-00 8-22-00 8-23-00	MIRU. SDON. TOOH w/pump & re Chemical cut TIH w/fishing t Washover fish t Latch onto fish TIH w/186 jts 2 pump & rods.	ods. ND WH. NU tbg @ 5770'. Tools. Fish for o PBTD @ 5881'. TOOH w/fishi 3/8" 4.7# J-5	ns BOP. Tbg s COOH w/2 3/8 tbg. SDON SDONng tools & 55 tbg, set	tuck. Freepo " tbg. SD fo	r weekend.
8-17-00 8-18-00 8-21-00 8-22-00 8-23-00 8-24-00	MIRU. SDON. TOOH w/pump & re Chemical cut TIH w/fishing t Washover fish t Latch onto fish TIH w/186 jts 2	ods. ND WH. NU tbg @ 5770'. Tools. Fish for o PBTD @ 5881'. TOOH w/fishi 3/8" 4.7# J-5	ns BOP. Tbg s COOH w/2 3/8 tbg. SDON SDONng tools & 55 tbg, set	tuck. Freepo " tbg. SD fo	r weekend.
8-17-00 8-18-00 8-21-00 8-22-00 8-23-00 8-24-00	MIRU. SDON. TOOH w/pump & re Chemical cut TIH w/fishing t Washover fish t Latch onto fish TIH w/186 jts 2 pump & rods.	ods. ND WH. NU tbg @ 5770'. Tools. Fish for o PBTD @ 5881'. TOOH w/fishi 3/8" 4.7# J-5	ns BOP. Tbg s COOH w/2 3/8 tbg. SDON SDONng tools & 55 tbg, set	tuck. Freepo " tbg. SD fo	r weekend.
8-17-00 8-18-00 8-21-00 8-22-00 8-23-00 8-24-00	MIRU. SDON. TOOH w/pump & re Chemical cut TIH w/fishing t Washover fish t Latch onto fish TIH w/186 jts 2 pump & rods. PT & pump actio	ods. ND WH. NU tbg @ 5770'. T ools. Fish for o PBTD @ 5881' . TOOH w/fishi 3/8" 4.7# J-5 SDON. on, OK. RD. Rig	ns BOP. Tbg s COOH w/2 3/8 tbg. SDON. SDON. Ing tools & tbg, set g released.	tuck. Freepo	r weekend.
8-17-00 8-18-00 8-21-00 8-22-00 8-23-00 8-24-00	MIRU. SDON. TOOH w/pump & re Chemical cut TIH w/fishing t Washover fish t Latch onto fish TIH w/186 jts 2 pump & rods.	ods. ND WH. NU tbg @ 5770'. T ools. Fish for o PBTD @ 5881' TOOH w/fishi 3/8" 4.7# J-5 SDON. on, OK. RD. Rig	TOP. Tbg some series of BOP. Tbg some series of tbg. SDON. Ing tools & some series of tbg, set of tbg. Set of tbg.	tuck. Freepo "tbg. SD fo fish. SDON. @ 5838'. ND	BOP. NU WH. TIH w/
8-17-00 8-18-00 8-21-00 8-22-00 8-23-00 8-24-00	MIRU. SDON. TOOH w/pump & re Chemical cut TIH w/fishing t Washover fish t Latch onto fish TIH w/186 jts 2 pump & rods. PT & pump actio	ods. ND WH. NU tbg @ 5770'. T ools. Fish for o PBTD @ 5881' TOOH w/fishi 3/8" 4.7# J-5 SDON. on, OK. RD. Rig	TOP. Tbg some series of BOP. Tbg some series of tbg. SDON. Ing tools & some series of tbg, set of tbg. Set of tbg.	tuck. Freepo "tbg. SD fo fish. SDON. @ 5838'. ND	r weekend.
8-17-00 8-18-00 8-21-00 8-22-00 8-23-00 8-24-00 8-25-00	MIRU. SDON. TOOH w/pump & re Chemical cut TIH w/fishing t Washover fish t Latch onto fish TIH w/186 jts 2 pump & rods. PT & pump actio	ods. ND WH. NU tbg @ 5770'. T cols. Fish for o PBTD @ 5881' . TOOH w/fishi 3/8" 4.7# J-5 SDON. on, OK. RD. Rig	TOP. Tbg some series of BOP. Tbg some series of tbg. SDON. Ing tools & some series of tbg, set of tbg. Set of tbg.	tuck. Freepo "tbg. SD fo fish. SDON. @ 5838'. ND	Date 8/28/00TLW