UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

		bundly not	tices and Reports on Wells	02	
			5:0 () 25	5.	Lease Number
					SF-078115
Тур€	of We	11	C 7.	6.	If Indian, All. or
c	AS		(50/83	200	Tribe Name
			65		
			JUN 2	7.	Unit Agreement Name
Name	e of Op	erator	E 2505000	- 54	
B^{l}	URL.	INGTON	\$ \frac{1}{2} \fra		
R	ESO	URCES OIL	& GAS COMPANY		
			.,3	<i>₹</i> 8.	Well Name & Number
Addı	cess &	Phone No. of Opera	ator Co.		Grenier #13E
		_	M 87499 (505) 326-9700277	<u>۶</u> ٠.	API Well No.
		, J			30-045-25332
Loca	ation o	f Well, Footage, S	Sec., T, R, M	10.	Field and Pool
			T-31-N, R-11-W, NMPM		Blanco MV/Basin DK
	·		· · · · · · · · · · · · · · · · · · ·	11.	County and State
					San Juan Co, NM
			NDICATE NATURE OF NOTICE, REPO	RT, OTHER	DATA
Type		bmission	Type of Action		
-	No	tice of Intent		inge of Pl	
				Construc	•
-	_X_ Su	bsequent Report			Fracturing
		•	Casing Repair Wat	er Shut o	F-F
-	Fi	nal Abandonment	Altering Casing Cor		
-	Fi	nal Abandonment			
			Altering Casing Cor _X_ Other - commingle		
	Describ	e Proposed or Comp	Altering Casing Cor _X_ Other - commingle pleted Operations		
4	Describ	e Proposed or Comp	Altering Casing Cor _X_ Other - commingle pleted Operations P. SDON.	version t	o Injection
4	Describ	e Proposed or Comp MIRU. ND WH. NU BO TOOH w/2 3/8" tbg.	Altering Casing Cor _X_ Other - commingle pleted Operations	version t	o Injection
4	Describ 4-6-00 4-7-00	e Proposed or Comp MIRU. ND WH. NU BO TOOH W/2 3/8" tbg. TOOH. ND BOP. NU	Altering Casing Cor _X_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE	e csg to	O Injection
4	Describ 4-6-00 4-7-00	MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085	Altering Casing Cor _X_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, , 5101, 5131, 5149, 5164, 5178, 5	e csg to 5008, 502	O Injection 3000 psi, OK. 2, 5026, 5039, 5201, 5212,
4	Describ 4-6-00 4-7-00	TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276	Altering Casing Cor _X_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, ,5101, 5131, 5149, 5164, 5178, 5 ,5283, 5289, 5315 w/27 0.32" dia	2 & csg to 5008, 502 5187, 5192,	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn &
4	Describ 4-6-00 4-7-00	Proposed or Comp MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout	Altering Casing Cor _X_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, ,5101, 5131, 5149, 5164, 5178, 5 ,5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4	P & csg to 5008, 502 5187, 5192, ameter hole	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP,
4	Describ 4-6-00 4-7-00	Proposed or Comp MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT	Altering Casing Cor _X_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, ,5101, 5131, 5149, 5164, 5178, 5 ,5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4 CIBP to 3000 psi, OK. Perf Cliffs	P & csg to 5008, 502 5187, 5192, ameter hole 10 Brady sn	O Injection 3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658,
4	Describ 4-6-00 4-7-00	Proposed or Comp MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT 4675, 4685, 4704	Altering Casing Cor _X_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, ,5101, 5131, 5149, 5164, 5178, 5 ,5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4	2 & csg to 5008, 502 5187, 5192, ameter hole 40 Brady sn house @ 462 4807, 4812,	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658, 4820, 4827,
4	Describ 4-6-00 4-7-00	Proposed or Comp MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT 4675, 4685, 4704 4833, 4839, 4886	Altering Casing CorX_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, , 5101, 5131, 5149, 5164, 5178, 5 , 5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4 CIBP to 3000 psi, OK. Perf Cliffe , 4713, 4724, 4765, 4771, 4801, 4	2 & csg to 5008, 502 5187, 5192, ameter hole 40 Brady sn house @ 462 4807, 4812,	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658, 4820, 4827,
4	Describ 4-6-00 4-7-00 4-12-00	Proposed or Comp MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT 4675, 4685, 4704 4833, 4839, 4886 w/1156 bbl slk w	Altering Casing CorX_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, , 5101, 5131, 5149, 5164, 5178, 5 , 5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4 CIBP to 3000 psi, OK. Perf Cliffe , 4713, 4724, 4765, 4771, 4801, 4 , 4891 w/19 0.32" diameter holes	S & csg to 5008, 502 5187, 5192, ameter hole 40 Brady sn house @ 462 4807, 4812, Brk dwn &	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658, 4820, 4827, frac Cliffhouse
4	Describ 4-6-00 4-7-00 4-12-00	Proposed or Comp MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT 4675, 4685, 4704 4833, 4839, 4886 w/1156 bbl slk w MIRU. ND WH. NU BO CO to CIBP @ 4922'	Altering Casing CorX_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, , 5101, 5131, 5149, 5164, 5178, 5, , 5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4 CIBP to 3000 psi, OK. Perf Cliffe , 4713, 4724, 4765, 4771, 4801, 4 , 4891 w/19 0.32" diameter holes ttr, 50,000# 20/40 Brady snd. RD.	2 & csg to 5008, 502 5187, 5192, ameter hole 10 Brady sn house @ 462 4807, 4812, Brk dwn &	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658, 4820, 4827, frac Cliffhouse Blow well.
4	Describ 4-6-00 4-7-00 4-12-00 4-14-00 4-15-00	MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT 4675, 4685, 4704 4833, 4839, 4886 w/1156 bbl slk w MIRU. ND WH. NU BO CO to CIBP @ 4922' well.	Altering Casing CorX_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, , 5101, 5131, 5149, 5164, 5178, 5 , 5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4 CIBP to 3000 psi, OK. Perf Cliffe , 4713, 4724, 4765, 4771, 4801, 4 , 4891 w/19 0.32" diameter holes tr, 50,000# 20/40 Brady snd. RD. P. TIH w/mill, tag up @ 4700'. Co	2 & csg to 5008, 502 5187, 5192, ameter hole 10 Brady sn house @ 462 4807, 4812, Brk dwn &	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658, 4820, 4827, frac Cliffhouse Blow well.
4	Describ 4-6-00 4-7-00 4-12-00 4-14-00 4-15-00	MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT 4675, 4685, 4704 4833, 4839, 4886 w/1156 bbl slk w MIRU. ND WH. NU BO CO to CIBP @ 4922' well. Blow well.	Altering Casing CorX_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, , 5101, 5131, 5149, 5164, 5178, 5 , 5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4 CIBP to 3000 psi, OK. Perf Cliffer, , 4713, 4724, 4765, 4771, 4801, 4 , 4891 w/19 0.32" diameter holes tr, 50,000# 20/40 Brady snd. RD. P. TIH w/mill, tag up @ 4700'. Co	2 & csg to 5008, 502 5187, 5192, ameter hole 10 Brady sn house @ 462 4807, 4812, Brk dwn &	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658, 4820, 4827, frac Cliffhouse Blow well. 5350'. Blow
4	Describ 4-6-00 4-7-00 4-12-00 4-14-00 4-15-00	MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT 4675, 4685, 4704 4833, 4839, 4886 w/1156 bbl slk w MIRU. ND WH. NU BO CO to CIBP @ 4922' well. Blow well. CO to C	Altering Casing CorX_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, , 5101, 5131, 5149, 5164, 5178, 5 , 5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4 CIBP to 3000 psi, OK. Perf Cliffe , 4713, 4724, 4765, 4771, 4801, 4 , 4891 w/19 0.32" diameter holes tr, 50,000# 20/40 Brady snd. RD. P. TIH w/mill, tag up @ 4700'. Co	2 & csg to 5008, 502 5187, 5192, ameter hole 10 Brady sn house @ 462 4807, 4812, Brk dwn &	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658, 4820, 4827, frac Cliffhouse Blow well. 5350'. Blow
4	Describ 4-6-00 4-7-00 4-12-00 4-14-00 4-15-00	MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT 4675, 4685, 4704 4833, 4839, 4886 w/1156 bbl slk w MIRU. ND WH. NU BO CO to CIBP @ 4922' well. Blow well.	Altering Casing CorX_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, , 5101, 5131, 5149, 5164, 5178, 5 , 5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4 CIBP to 3000 psi, OK. Perf Cliffer, , 4713, 4724, 4765, 4771, 4801, 4 , 4891 w/19 0.32" diameter holes tr, 50,000# 20/40 Brady snd. RD. P. TIH w/mill, tag up @ 4700'. Co	2 & csg to 5008, 502 5187, 5192, ameter hole 10 Brady sn house @ 462 1807, 4812, Brk dwn & 0 to 4900'. 0 to CIBP @	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658, 4820, 4827, frac Cliffhouse Blow well. 5350'. Blow
4	Describ 4-6-00 4-7-00 4-12-00 4-14-00 4-15-00 4-16-00 4-17-00	MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT 4675, 4685, 4704 4833, 4839, 4886 w/1156 bbl slk w MIRU. ND WH. NU BO CO to CIBP @ 4922' well. Blow well. Blow well. CO to C	Altering Casing CorX_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, , 5101, 5131, 5149, 5164, 5178, 5, , 5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4 CIBP to 3000 psi, OK. Perf Clifff, , 4713, 4724, 4765, 4771, 4801, 4 , 4891 w/19 0.32" diameter holes ttr, 50,000# 20/40 Brady snd. RD. P. TIH w/mill, tag up @ 4700'. Co	2 & csg to 2 & csg to 3 5008, 502 5187, 5192, ameter hole 40 Brady sn house @ 462 4807, 4812, Brk dwn & 5 to 4900'. 5 to CIBP @ 6 5350'. C	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658, 4820, 4827, frac Cliffhouse Blow well. 5350'. Blow
4	Describ 4-6-00 4-7-00 4-12-00 4-14-00 4-15-00 4-16-00 4-17-00	MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT 4675, 4685, 4704 4833, 4839, 4886 w/1156 bbl slk w MIRU. ND WH. NU BO CO to CIBP @ 4922' well. Blow well. Blow well. CO to C	Altering Casing CorX_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, , 5101, 5131, 5149, 5164, 5178, 5 , 5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4 CIBP to 3000 psi, OK. Perf Cliffer, , 4713, 4724, 4765, 4771, 4801, 4 , 4891 w/19 0.32" diameter holes tr, 50,000# 20/40 Brady snd. RD. P. TIH w/mill, tag up @ 4700'. Co	2 & csg to 2 & csg to 3 5008, 502 5187, 5192, ameter hole 40 Brady sn house @ 462 4807, 4812, Brk dwn & 5 to 4900'. 5 to CIBP @ 6 5350'. C	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658, 4820, 4827, frac Cliffhouse Blow well. 5350'. Blow
.4.	Describ 4-6-00 4-7-00 4-12-00 4-12-00 4-15-00 4-16-00 4-17-00	MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT 4675, 4685, 4704 4833, 4839, 4886 w/1156 bbl slk w MIRU. ND WH. NU BO CO to CIBP @ 4922' well. Blow well. Blow well. CO to C	Altering Casing Cor_ _X_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, , 5101, 5131, 5149, 5164, 5178, 5 , 5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4 CIBP to 3000 psi, OK. Perf Clifff, , 4713, 4724, 4765, 4771, 4801, 4 , 4891 w/19 0.32" diameter holes ttr, 50,000# 20/40 Brady snd. RD. P. TIH w/mill, tag up @ 4700'. Co P. TIH w/mill, tag up @ 4700'. Co EIBP @ 5350'. Blow well. D/O CIBP	2 & csg to 2 & csg to 3 5008, 502 5187, 5192, 5187, 5192, 5187, 5192, 5187, 5192, 5180 Brady sn 5100	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658, 4820, 4827, frac Cliffhouse Blow well. 5350'. Blow
4	Describ 4-6-00 4-7-00 4-12-00 4-12-00 4-15-00 4-16-00 4-17-00	MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT 4675, 4685, 4704 4833, 4839, 4886 w/1156 bbl slk w MIRU. ND WH. NU BO CO to CIBP @ 4922' well. Blow well. Blow well. CO to C	Altering Casing CorX_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, , 5101, 5131, 5149, 5164, 5178, 5, , 5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4 CIBP to 3000 psi, OK. Perf Clifff, , 4713, 4724, 4765, 4771, 4801, 4 , 4891 w/19 0.32" diameter holes ttr, 50,000# 20/40 Brady snd. RD. P. TIH w/mill, tag up @ 4700'. Co	2 & csg to 2 & csg to 3 5008, 502 5187, 5192, 5187, 5192, 5187, 5192, 5187, 5192, 5180 Brady sn 5100	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658, 4820, 4827, frac Cliffhouse Blow well. 5350'. Blow to 7216'. Flow ted on back te 4/25/00
4.	Describ 4-6-00 4-7-00 4-12-00 4-14-00 4-15-00 4-16-00 4-17-00	MIRU. ND WH. NU BOY TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT 4675, 4685, 4704 4833, 4839, 4886 w/1156 bbl slk w MIRU. ND WH. NU BOY CO to CIBP @ 4922' well. Blow well. Blow well. CO to Could be the count Blow well. Could be the count Blow well. Could be the count County that the count County that the	Altering Casing CorX_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, , 5101, 5131, 5149, 5164, 5178, 5, , 5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4 CIBP to 3000 psi, OK. Perf Clifff, , 4713, 4724, 4765, 4771, 4801, 4 , 4891 w/19 0.32" diameter holes tr, 50,000# 20/40 Brady snd. RD. P. TIH w/mill, tag up @ 4700'. Co . Flow well. D/O CIBP @ 4922'. Co CIBP @ 5350'. Blow well. D/O CIBP e foregoing is true and correct Title Regulatory Adminis	2 & csg to 2 & csg to 3 5008, 502 5187, 5192, 5187, 5192, 5187, 5192, 5187, 5192, 5180 Brady sn 5100	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658, 4820, 4827, frac Cliffhouse Blow well. 5350'. Blow to 7216'. Flow ted on back te 4/25/00
4.	Describ 4-6-00 4-7-00 4-12-00 4-12-00 4-15-00 4-16-00 4-17-00	MIRU. ND WH. NU BO TOOH w/2 3/8" tbg. TOOH. ND BOP. NU RU. Perf Pt Lookout 5052, 5072, 5085 5218, 5240, 5276 frac Pt Lookout set @ 4922'. PT 4675, 4685, 4704 4833, 4839, 4886 w/1156 bbl slk w MIRU. ND WH. NU BO CO to CIBP @ 4922' well. Blow well. Blow well. CO to C	Altering Casing CorX_ Other - commingle pleted Operations P. SDON. TIH w/CIBP, set @ 5350'. PT CIBE WH. RD. Rig released. t @ 4941, 4955, 4984, 4993, 5002, , 5101, 5131, 5149, 5164, 5178, 5, , 5283, 5289, 5315 w/27 0.32" dia w/2180 bbl slk wtr, 100,000# 20/4 CIBP to 3000 psi, OK. Perf Clifff, , 4713, 4724, 4765, 4771, 4801, 4 , 4891 w/19 0.32" diameter holes tr, 50,000# 20/40 Brady snd. RD. P. TIH w/mill, tag up @ 4700'. Co . Flow well. D/O CIBP @ 4922'. Co CIBP @ 5350'. Blow well. D/O CIBP e foregoing is true and correct Title Regulatory Adminis	2 & csg to 2 & csg to 3 5008, 502 5187, 5192, 5187, 5192, 5187, 5192, 5187, 5192, 5180 Brady sn 5100	3000 psi, OK. 2, 5026, 5039, 5201, 5212, s. Brk dwn & d. TIH w/CIBP, 2, 4629, 4658, 4820, 4827, frac Cliffhouse Blow well. 5350'. Blow to 7216'. Flow ted on back te 4/25/00

FARMINGTON FIELD UPFICE

4-18-00 Flow well. CO to PBTD @ 7216'. TOOH w/mill. Flow well.
4-19-00 Flow well. TIH w/228 jts 2 3/8" 4.7# J-55 tbg, set @ 7151'. ND BOP. NU WH.
RD. Rig released.

Well will operate as a MV/DK commingle under DHC #2562.

on Mag