REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE

PULL OR ALTER CASING

MULTIPLE COMPLETE

REPAIR WELL

CHANGE ZONES ABANDON*

(other)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a differ reservoir. Use Form 9–331–C for such proposals.)

	Budget Bureau No. 42-R1424		
	5. LEASE		
	NM-013688		
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
ent	7. UNIT AGREEMENT NAME		
	8. FARM OR LEASE NAME Atlantic "A"		
	9. WELL NO. 101		
	10. FIELD OR WILDCAT NAME East Aztec		
17	11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA 22-31N-10W		
	12. COUNTY OR PARISH San Juan	13. STATE New Mexico	
Έ,	14. API NO. 30-045-25340		
	15. ELEVATIONS (SHOW	DF, KDB, AND WD)	

1. oil gas X well other well ARCO Oil and Gas Company 2. NAME OF OPERATOR Division of Atlantic Richfield Company 3. ADDRESS OF OPERATOR P. O. Box 5540, Denver, Colorado 80217 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1 below.) 1030' FSL & 1040' FEL AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH: Approx the same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTIC REPORT, OR OTHER DATA

> RECEIVE (NOTE: Report results of multiple completion or zone ange on Form 9-330.) MAY 21 1982

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

FARMINGTON, N. W

SUBSEQUENT REPORT OF:

NO SETTING PRODUCTION CASING S. CLOLUSINAL SUCCESSION

Drilled to 7794'. Logged. RU & ran 179 jts (7794.01') 4-1/2", 11.6#, N-80, LT&C casing and set @ 7793'. Circl casing with mud for 1 hour, pumped 10 bbls mud flush. Cemented 1st stage with 225 sx lite, 6# salt/sx, 12-1/2# gilsonite/sx, .5% CFR-2 followed by 125 sx 50/50 poz mix A Class "H", 6# salt/sx, .75% CFR-2. Displaced plug with 32 BW & 88 BM - full returns. PD @ 5:10 pm 5-12-82. Dropped bomb and open lower stage tool. Circl. Pumped 10 bbls mud flush. Cemented 2nd stage with 450 sx lite, 6# salt/sx, 6-1/4# gilsonite.sx, 2% CaCl₂, .5% CFR-2. Displaced plug with 33 BW & 53 BM. PD @ 10:02 pm 5-12-82. Dropped bomb & open upper stage tool. Circl. Pumped 10 bbls mud flush and cemented 3rd stage with 1050 sx lite, 6# salt/sx, 6-1/4# gilsonite/sx, 2% CaCl₂, .5% CFR-2. PD @ 1:55 am 5-13-82. Set casing hanger and cut off casing, Réleased rig 5-13-82. WO Completion.

Subsurface Safety Valve: Manu. and Type	Set @ F
18. I hereby certify that the foregoing is true and correct	
SIGNED W.A. Walther, Jr. Plant District Manager DATE Of Production	5-18-82
(This space for Federal or State office use)	
APPROVED BY TITLE DATE CONDITIONS OF APPROVAL, IF ANY:	ASSEPTED FOR RECORD
*See Instructions on Reverse, Signature	MAY 25 1982
OIL DIST. 3	FARMINGTON DISTRICT BY
NMOCG	