FOT DISTRICT ENGINEER

UNITED STATES DEPARTMENT OF THE INTERIOR

UNITED STATES	5. LEASE ខែទី១១ ១ ភូគីគ 14-20-603-65 គឺគឺ ជ ក្នុងគ្
DEPARTMENT OF THE INTERIOR	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo Tribal (ま) というなった。
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME : 5 d g
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	
1. oil gas	8. FARM OR LEASE NAME இத்தில் Navajo "U" இத்தி நிருந்வ
well X well other	9. WELL NO STEEL STEEL
2. NAME OF OPERATOR	7 January Lace
Energy Reserves Group, Inc. 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Horseshoe-Gallup
P.O. Box 3280 - Casper, Wyoming 82602	Horseshoe-Gallup = 😤 👼 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA 충돌경로 6 교육경호
below.) AT SURFACE: 990' FNL & 2,310' FWL	Section 5-T31N-R17W 결혼급축
AT TOP PROD. INTERVAL:	San Juan 3,57 New Mexico
AT TOTAL DEPTH:	14. API NO. 3 19 19 19 19 19 19 19 19 19 19 19 19 19
L6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	TE CLEVETIONS (SUSSEED)
il and the same of	15. ELEVATIONS (SHOW DF, KDB, AND WD) G.L. 9,333'; K.B. 5,338'
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	- 0 16 0 - n 20
DAGTURE TREAT	Toget be add toget be add toget be ad blue and b
SHOOT OR ACIDIZE REPAIR WELL CNOTE Report results of multiple completion or zone	
PULL OR ALTER CASING Change on Form 9-330.)	
	change on Form 9–330.) Consider the property of the property o
ABANDON* X DU. S. GEOLOGICAE SOI	girol britten girol britten girol britten girol britten girl lie well melbat te eleb grann girol britten britt
other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	
্টিছিল ভূ বুট্টিট The Tocito was opened from 1,114'-1,124' w/2 JSPF, Acidized w/500 gal 7-1/2%	
HCl, & Frac'd w/16,750 gal 75% Quality Foam w/24,000 lbs 10-20 sd. The zone	
proved to be nonproductive. Energy Reserves Group, Inc. proposes to plug	
the well by placing 200' of cement across the perfs, and a 100' cement plug at surface and install a dry hole marker.	
	Should Hand
Verbal approval was obtained from Mr. Steve Mason with the Minerals Management in Farmington on May 20, 1982.	
In Parinington on Play 20, 1902.	igned for submitten to specify the solution to save the second to solve the solution of the so
	de de la company
	bengin elden fit. bengin elden i such such such such such such such such
Subsurface Safety Valve: Manu. and Type	Set @ 10 15 2 Ft.
18. I hereby certify that the foregoing is true and correct	Set Us of one of the base of the base of one of the base of one of the base of one of the base of t
SIGNED TITLE Prod. Engr - I	RMD_ pare 5_20_82 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등
(This space for Federal or State of the	(설립시 17 년 1월 7년 e wset - 국물 6월 1 일 4 기업류
(This space for Federator State of Stat	ATE DESCRIPTION OF THE PROPERTY OF THE PROPERT
CONDITIONS OF APPROVAL, IF ANY:	- 連続 / - 3.5.5.2.7 おから A. S.
	island in the second of the se
	1062 THE STANDARY TO SEE THE STANDARY TO SEE THE SEE T

MWOCQ,