Budget Bureau No. 1004-0135 Form 3160-5 (November 1983) UNITED STATES SUBMIT IN TRIPLICATE. Expires August 31, 1985 DEPARTMENT OF THE INTERIOR (Other Instructions on 5. LEASE DESIGNATION AND SERIAL NO. (Formerly 9-331) 14 20 403 203**3** BUREAU OF LAND MANAGEMENT 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) Navajo Tribal 7. UNIT AGREEMENT NAME WELL X OTEER 8. FARM OR LEASE NAME 2. NAME OF OPERATOR Navajo Tribe of Indians **G** Solar Petroleum, Inc. 9. WBLL NO. 3. ADDRESS OF OPERATOR 227 1099 18th street suite 2900 Denver, Co. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface 10. FIELD AND POOL, OR WILDCAT Horseshoe Gallup RECEIVED 11. SBC., T., R., M., OR BLE. AND SURVEY OR AREA 1310 FWL 1330FSL AUG 08 1984 Sec ! T31N R17W 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH 18. STATE 14. PERMIT NO. 5154 BUREAU OF LA JOURNAL OF MENT New Mexico San Juan 16 Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

WATER SHOT-OFF

FRACTURE TREATMENT

SECOTING OR ACIDIZING

(Other) TA procedure

Surf csg 85/6"@ 86 4L

NOTICE OF INTENTION TO:

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON *

CHANGE PLANS

Prod csg 5/2"@ 912GL

The 2 1/8 @ 925 GL

Perfs 912-928

TD 928

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

Procedure: MI service rig Pull tbg, rods & pump RIH w/ tbg, displace 25 sx cement 10' above perfs Pull tbg to top of cement Displace hole w/ 9.2# mud to surface Pull tbg to 100+. Keep hole full w/ mud Displace 25 sx cement to surface Pull tbg LD tbg Clean up location, move to next location

AUG 1 6 1984

SUBSECUENT REPORT OF :

REPAIRING WELL

ALTERING CABING

ABANDON MENT

OIL CON. DIV. DIST. 3

This Approval Or Temporary aby-topment Expires

%		
18. I hereby certify that the foregoing is true and correct SIGNED Marie O Keefe	TITLE Engineering Technic	cian APBROVEP84
U		AS AMENDED
(This space for Federal or State office use)		AS I
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	AUPGT 4 1984
CONDITIONS OF MITTHE AT THE	NMOCC	M. MILLENBACH WAREA MANAGER
*Se	e Instructions on Reverse Side	WAREA MANAGER