

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL OTHER-	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name Keys Gas Com G
3. Address of Operator 501 Airport Dr., Farmington, NM 87401	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> <u>1480</u> FEET FROM THE <u>South</u> LINE AND <u>1620</u> FEET FROM THE <u>West</u> LINE, SECTION <u>27</u> TOWNSHIP <u>32N</u> RANGE <u>10W</u> NMPM.	10. Field and Pool, or Wildcat Mt. Nebo Fruitland Ext.
11. Elevation (Show whether DF, RT, GR, etc.)	12. County San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Completion</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Completion operations commenced on 11-29-82. Total depth of the well is 2759' and completed open hole. Cleaned out hole with 2-7/8" buttress tubing. Tripped into hole with Gravel Pack assembly and landed at 2759'. Set Pengo tools at 2513' to 2479'. Gravel packed behind Pengo tools. Ran 2-7/8" tubing with downhole pump to 2605'. Release the rig on 12-13-82. Presently testing the well.

CONFIDENTIAL

FILED
DEC 9

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Admin. Supvr. DATE 3-3-83

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: