

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Budget Bureau No. 1004-0115
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
SF-078604A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☐ GAS WELL ☒ OTHER

CONFIDENTIAL

2. NAME OF OPERATOR

Amoco Production Co.

3. ADDRESS OF OPERATOR

501 Airport Drive, Farmington, N M 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1645' FNL X 1615' FEL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Ealum Gas Com C

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Cedar Hill Fruitland Basal Coal

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

SW/NE Sec 33, T32N, R10W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

RECEIVED

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)
5995' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

TEST WATER

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

RELL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHOT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Moved in and rigged up service unit on 10-1-85. Attempted to pull gravel pack assembly and the gravel pack tool became stuck after being pulled 60 feet. Milled through packer and attempted recover the tool with grapples and a casing spear. After the casing spear would not release, the tubing was shot and backed off. Remaining in the hole are two subs, a casing spear and gravel pack assembly. The fish is from 2525'-2664'. The open hole interval is from 2769'-2805'. Landed 2 7/8" tubing at 2489' and released the rig on 10-11-85.

RECEIVED
NOV 06 1985
OIL CON. DIV.
DIST. 3

FARMINGTON DISTRICT	
NOV 1 1985	
RJB	
DDL	
OBB	
GOM	
TWE	
EDS	
SMH	
BY	
TLB	

ACCEPTED FOR RECORD

OCT 31 1985

FARMINGTON RESOURCE AREA

CONFIDENTIAL

*See Instructions on Reverse Side

NMOCC