

4. Maintain Strict Quality control guidelines with the service company, get viscosity checks, Sand fines Sieve Analysis, cloudiness of gelled System etc.

5. Dump down in 500' increments.