UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

		Sunary Notice	ces and Reports on Wells		
				-Fil-1:34 ₅	
			200 1111	5.	Lease Number
			<u> </u>	Commercial group	SF-078604 If Indian, All. or
. Tvp	e of Well		हिन्दुर्गी अवस्थित्यक्षेत्रकारी	6.	
	GAS				Tribe Name
	GAD				
				7.	Unit Agreement Nam
Mam	e of Oper	ator	1.		
-B	URLI	NGTON RCES			
K	ESOU	ACES OIL	GAS COMPANY	•	Well Name & Number
				8.	
. Add	lress & Ph	one No. of Operat	or		Scott #101
PC	Box 4289	, Farmington, NM	87499 (505) 326-9700	9.	API Well No.
	2011	,			30-045-26841
Loc	ation of	Well, Footage, Se	C., T. R. M	10	. Field and Pool
:. <u>1</u> 00	OLEM 14	ENTER Sec 31	'-32-N, R-10-W, NMPM		Cedar Hill FC
157	70'ENL, 14	30 EEU, DCC.JI, "	32 11, 10 20 11, 11-11-1	11	. County and State
					San Juan Co, NM
			TOTAL MARINE OF MORICE	DEDUDT UTHE	P DATA
			CATE NATURE OF NOTICE,	ABEORI, OILL	
Tyr	e of Subm		Type of Action		1
	Noti	ce of Intent		Change of P	
			Recompletion	New Constru	
	X Subs	sequent Report	Plugging Back	Non-Routine	
	- -	-	Casing Repair	Water Shut	
	## m =	al Abandonment	Altering Casing	a	to Injection
			Altering casing	Conversion	to injection
	FIRE	AT ADMITCHIC			to injection
	Fina	ar Abandonment	X_ Other - pump instal		to injection
			X Other - pump instal		
13.		Proposed or Compl	X Other - pump instal		
13.	Describe	Proposed or Compl	X Other - pump instal	lation 	·
13.	Describe	Proposed or Compl	X Other - pump instal	TOOH w/2 3/8	" tbg. SDON.
13.	Describe	Proposed or Compl	X Other - pump instal	TOOH w/2 3/8	" tbg. SDON. H w/93 jts 2 3/8"
13.	Describe	Proposed or Compl IRU. ND WH. NU BO IH w/mill. Circ 8 4.7# J-55 tbg, 8	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W	TOOH w/2 3/8	" tbg. SDON. H w/93 jts 2 3/8"
L3.	Describe	Proposed or Compl	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W	TOOH w/2 3/8	" tbg. SDON. H w/93 jts 2 3/8"
13.	Describe	Proposed or Compl IRU. ND WH. NU BO IH w/mill. Circ 8 4.7# J-55 tbg, 8	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W	TOOH w/2 3/8	" tbg. SDON. H w/93 jts 2 3/8"
13.	Describe	Proposed or Compl IRU. ND WH. NU BO IH w/mill. Circ 8 4.7# J-55 tbg, 8	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W	TOOH w/2 3/8	" tbg. SDON. H w/93 jts 2 3/8"
13.	Describe	Proposed or Compl IRU. ND WH. NU BO IH w/mill. Circ 8 4.7# J-55 tbg, 8	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W	TOOH w/2 3/8	" tbg. SDON. H w/93 jts 2 3/8"
13.	Describe	Proposed or Compl IRU. ND WH. NU BO IH w/mill. Circ 8 4.7# J-55 tbg, 8	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W	TOOH w/2 3/8	" tbg. SDON. H w/93 jts 2 3/8"
13.	Describe	Proposed or Compl IRU. ND WH. NU BO IH w/mill. Circ 8 4.7# J-55 tbg, 8	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W	TOOH w/2 3/8	" tbg. SDON. H w/93 jts 2 3/8"
13.	Describe	Proposed or Compl IRU. ND WH. NU BO IH w/mill. Circ 8 4.7# J-55 tbg, 8	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W	TOOH w/2 3/8	" tbg. SDON. H w/93 jts 2 3/8"
13.	Describe	Proposed or Compl IRU. ND WH. NU BO IH w/mill. Circ 8 4.7# J-55 tbg, 8	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W	TOOH w/2 3/8	" tbg. SDON. H w/93 jts 2 3/8"
13.	Describe	Proposed or Compl IRU. ND WH. NU BO IH w/mill. Circ 8 4.7# J-55 tbg, 8	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W	TOOH w/2 3/8	" tbg. SDON. H w/93 jts 2 3/8"
13.	Describe	Proposed or Compl IRU. ND WH. NU BO IH w/mill. Circ 8 4.7# J-55 tbg, 8	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W	TOOH w/2 3/8	" tbg. SDON. H w/93 jts 2 3/8"
13.	Describe	Proposed or Compl IRU. ND WH. NU BO IH w/mill. Circ 8 4.7# J-55 tbg, 8	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W	TOOH w/2 3/8	" tbg. SDON. H w/93 jts 2 3/8"
13.	Describe	Proposed or Compl IRU. ND WH. NU BO IH w/mill. Circ 8 4.7# J-55 tbg, 8	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W	TOOH w/2 3/8	" tbg. SDON. H w/93 jts 2 3/8"
13.	Describe 4-4-00 N 4-6-00 T	Proposed or Compl IRU. ND WH. NU BO IIH w/mill. Circ 8 4.7# J-55 tbg, 8 action, OK. RD.	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W Rig released.	TOOH w/2 3/8 H w/mill. TI H. TIH w/pum	" tbg. SDON. H w/93 jts 2 3/8"
	Describe 4-4-00 N 4-6-00 T	Proposed or Compl IRU. ND WH. NU BO IIH w/mill. Circ 8 4.7# J-55 tbg, 8 action, OK. RD.	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W Rig released.	TOOH w/2 3/8 H w/mill. TI H. TIH w/pum	" tbg. SDON. H w/93 jts 2 3/8"
13.	Describe 4-4-00 N 4-6-00 T	Proposed or Compl IRU. ND WH. NU BO IIH w/mill. Circ 8 4.7# J-55 tbg, 8 action, OK. RD.	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W	TOOH w/2 3/8 H w/mill. TI H. TIH w/pum	" tbg. SDON. H w/93 jts 2 3/8"
14.	Describe 4-4-00 M 4-6-00 T	Proposed or Compl IRU. ND WH. NU BO IIH w/mill. Circ 8 4.7# J-55 tbg, 8 action, OK. RD.	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W Rig released.	TOOH w/2 3/8 H w/mill. TI H. TIH w/pum	" tbg. SDON. H w/93 jts 2 3/8" p & rods. PT & pump
14.	Describe 4-4-00 M 4-6-00 T	Proposed or Compl IRU. ND WH. NU BO IIH w/mill. Circ 8 4.7# J-55 tbg, 8 action, OK. RD.	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W Rig released.	TOOH w/2 3/8 H w/mill. TI H. TIH w/pum	" tbg. SDON. H w/93 jts 2 3/8" p & rods. PT & pump
14. Signe	Describe 4-4-00 M 4-6-00 T	Proposed or Complaint of the Will Mind Mind Mind Mind Mind Mind Mind Mind	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W Rig released. foregoing is true and co	TOOH w/2 3/8 H w/mill. TI H. TIH w/pum	" tbg. SDON. H w/93 jts 2 3/8" p & rods. PT & pump APR 2000 APR 2000 APR 2000
14. Signe	Describe 4-4-00 M 4-6-00 T	Proposed or Compl IRU. ND WH. NU BO IIH w/mill. Circ 8 4.7# J-55 tbg, 8 action, OK. RD.	_X_ Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. A CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W Rig released. Title Regulatory Admi e Office use)	TOOH w/2 3/8 H w/mill. TI H. TIH w/pum	" tbg. SDON. H w/93 jts 2 3/8" p & rods. PT & pump APR 2000 APR 2000 TLW
14. Signe (This	Describe 4-4-00 M 4-6-00 T I hereby d space for	Proposed or Complaint of the Will Mind Mind Mind Mind Mind Mind Mind Mind	X Other - pump instal Leted Operations OP. TIH, tag up @ 2950'. CO to PBTD @ 2963'. TOO Set @ 2959'. ND BOP. NU W Rig released. foregoing is true and co	TOOH w/2 3/8 H w/mill. TI H. TIH w/pum	" tbg. SDON. H w/93 jts 2 3/8" p & rods. PT & pump APR 2000 APR 2000

AHmin