UNITED STATES DEPARTMENT OF THE INTERIOR

	DE	PARTMENT OF	THE INTERIOR MANAGEMENT		,0705W50
				Walls	<u>RECEIVED</u> BLM
	Sundry	Notices and	Reports on		
. Type of W	Mell NAS	TO E GE	1991.	SF-0 6. If 1 Trib	ndian, Allyofol, HM oe Name Agreement Name
	Operator Oil Inc. & Phone No. 0 9, Farmingtor	OR CON	1. DIV.)	Çed	l Name & Number ar Hill SWD #1 Well No.
4. Location 830'N, 1	of Well, Foo	tage, Sec, T,	R,M. -10-W, NMPM	11.Cou	inty and State Juan County, NM
Type of Subscript	omission ce of Intent equent Report	Al Re Pi Ca	oandonment ecompletion Lugging Back asing Repair Ltering Casi	Nev	REPORT, OTHER DATA ange of Plans Construction -Routine Fracturin ter Shut Off nversion to Injection
13. Descri 07-30-91 07-31-91 08-01-91 08-02-91 08-03-91 08-04-91 08-05-91	7685'. Pull TIH w/gge r profile nip tbg. Flowed Run mill, t work up to Ran gge rin equipment & Snub out the Snub out w/	ow to pit. I gge ring. ing to 7690' ple @ 7685' ND WH. NU ag up @ 7672 7101'. Unabl g & blanking PT. Strip g. Snub in to fish. Flow spot @ 8457 OH w/scraper	Ran gge ring Flow to pit TOOH. Fl TOOH. Left BOP. TOOH Top of ple to get away plug set @ out tbg. W/fishing too	ow to ping setting w/tbg. To lug @ 76 ay from prome to 1008'. To lub in ho it. Tag	
14. I he	reby certify	that the fo	regoing is t		
	BY		office use)	ACCE	PTED FOR RECORD DATE AUG 80 1991
CONDITIO	N OF APPROVAL	1, II III			THE TOU BESOURCE AREA

FARMINGTON RESOURCE AREA

Cedar Hill SWD #1, cont'd.

- 08-06-91 Set RBP @ 7680'. ND BOPs. NU tbg head. PT 5000#/15 min, ok. TIH, circ. Released BP. Flow to pit. TIH w/BP to 7867', could not get below. TIH w/retrieving head on tbg to retrieve BP. 08-07-91
- TIH, tag BP @ 7439'. TOOH w/BP. TIH, mill inside of 7" csg 7867-75'. TOOH. TIH, mill on 7" csg 7875-7985'.
- 08-08-91 Mill in 7" csg to 8368'. TOOH. TIH, mill 8368-8681'. Btm perf @ 08-09-91
- Set RBP @ 8120'. Flow test. Set RBP @ 8375'. Flow test. TOOH w/RBP. Ran GR-CCL 8660-7660'. Perf Entrada 8446-8654' w/4 spf; Bluff 8161-8310' w/4 spf; Morrison 7707-8092' w/4 spf. TIH
- 08-10-91 Set SAP tool @ 8669-8680', would not test. Set @ 7680', would not test. PT tbg 3160#/5 min, ok. LD SAP tool. Set SAP tool @ 7680', unable to test. Flow back. TOOH. Bull plug btm of pkr. TIH to 4700'. SAP tool not holding. Test backside 2000#, ok. 08-11-91
- LD tool. TIH, straddle perf 8654-8161' w/RBP & ret pkr. 08-12-91
- Frac w/260,000#20/40 sand and 152,212 gal. fluid. Flow back. 08-13-91
- Flow to pit. Circ well.
- Ran after frac log 7660-8660'. TIH, wireline broke, fishing. 08-14-91 08-15-91 Fishing.
- 08-16-91 TOOH w/fish. Set pkr @ 7666'. Land 260 jts 3 1/2", 9.3#, N-80 8rd EUE tbg @ 7688'. ND BOP. 08-17-91
- PT 1000#/15 min, ok. Released rig.