Ferm 3160-5 (November 1983) (Furmerly 9-331)		UNITED STA TMENT OF TH EAU OF LAND MA	E INTERIO	SUBMIT IN TRIPLICATION ON (Other instructions on tweese side)	Expires Anons	N AND BERIAL	
SUN	DRY NC	OTICES AND RIPORALE TO DESCRIPTION FOR PERMIT	EPORTS O	N WELLS ck to a different reservoir.	O IF INDIAN, ALLOPI	BE UR IBIDE TE	
1. OIL GAS [					7. UNIT AGREEMENT P	AME	
WELL WELL	8. FARM OR LEASE NAME						
Richmond Petro	Federal 32-8-26						
2651 N. Harwoo  4. Location of Well (R. See also space 17 belo At surface	10. FIELD AND POOL OR WILDCAT Basin Fruitland Coal Gas						
840' FNL and 8	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA						
					Sec. 26, T3		
14. PERMIT NO.		15 ELEVATIONS (S	how whether DF.	RT, GR. etc.)	12. COUNTY OR PARIS San Juan	H 13. STATE NM	
16.		• •	o Indicate No	ature of Notice, Report, or			
N	OTICE OF INT	rention to:	,		QUENT BEPORT OF:		
TEST WATER SHUT-OF	<b>T</b>	PULL OR ALTER   AST	×6	WATER SHUT-OFF	REPAIRING	1	
FRACTURE TREAT		MILITIPLE COMPLETE		FRACTURE TREATMENT	ALTERING	;- <del></del>	
SHOOT OR ACIDIZE		ABANDÓN*	;	SHOOTING OR ACIDIZING	i OD	X	
REPAIR WELL		CHANGE PLANS		Other: Completion X  Note: Report results of multiple completion on Well			
proposed work If nent to this work.	wen is dure	ctio <b>nal</b> ly drilled, give s	eubsurfâce locati	details, and give pertinent dat ons and measured and true veri	ical depths for all marke	rs and zones perti-	
				DENTIAL			
					D E C E I	AEW	
					OCT 3 0 1	asa fr	
	 5						
	:				OIL CON. DIST.		
18. I hereby certify fast	the foregoin	g ly truefand correct					

\*See Instructions on Reverse Side

Title 18 U.S.C. Section 1991, makes it a drime for any person knowingly and willfully to make to any department or agency of the United States any talke, dictitious or fraudulent statements or representations as to any matter within its jurisdiction.

# CONFIDENTIAL

#### FEDERAL 32-8-26 No. 1

August 30, 1989 - Day No. 6

TD: 3,120' K.B.

Current Operation: Picking up drill pipe. Wilson Service Co. ran temperature survey - TOC - 1,000' KB. Nipple up BOP's, blooey line manifold and drilling head. Test BOP's to 2,500 psi. Nipple up choke manifold. Pick up drill collars and 3-1/2" drill pipe.

Rig time: Run temperature survey - 1:00
Put on tubing hangers - 1:30

Rig up BOP and blooey lines, rig up to complete - 12:15

Pressure test BOP w/ Quadco - 4:45

Pick up drill pipe and drill collars - 4:30

## August 31, 1989 - Day No. 6

TD: 3,496' K.B.

Current Operation: Drilling. Wt. on bit: 15,000, RPM: 40, Pump pressure 500 psi, SPM: 30, Mud vis: H<sub>2</sub>O and air. Pick up 3-1/2" drill pipe. Tag cement @ 3,120'. Drill out cement, float collar @ 3,138', and shoe @ 3,178' with fresh water. Drill out from under casing to 3,210'. Rig up 7" blooey lines. Rig up air compressors. Continue drilling with fresh water and air mixture. First drilling break @ 3,248' - continue drilling. (AMM)

Mudlogger report:

3,245' - 50' Shaly coal, no detectable gas 3,345' - 48' Shaly coal, no detectable gas 3,470' - 3,500' Clean coal - good gas show Clean coal - gas increase over background

Rig time: Pick up drill pipe - 1:00

Drill cement and cement shoe - 4:15

Rig up blooey lines - 3:15 Rig up with air - 1:00 Drilling - 14:30

## September 1, 1989 - Day No. 7

TD: 3,600' K.B.

Current Operation: Gauge well. Drilled 104 feet in the last 24 hours.

Rig time: Drilling - 3:15

Circulating - 2:00

Take off flow line - Blanket off - :30

Blow well - 10:00

TOH - :45 TIH - :15

Pressure up on well, test to 1,050 psi. - :45

Gauge well - 5:00

Wash to bottom - 150' fill - 1:30

#### September 2, 1989 - Day No. 8

TD: 3,600' K.B.

Current Operation: Blow well. Surging coal intervals @ 3,470' - 3,500'. Pumping 15 Bbls  $\rm H_2O$  every 25 min. Continue air @ rate of

# FEDERAL 32-8-26 No. 1 - cont.

1600 cu. ft/min. Returns were 8\$% coal, 15% shale. (AMM)
Rig time: Shut well in - building pressure to 100 psi - 1:00
TIH - :30
Blow well with air - 22:30

#### September 3, 1989

TD: 3,600' K.B.

Current Operation: Continue surging coal intervals @ 3,470' - 3,500'. Clean out to 3,530'. Well producing more coal and water than air compressor could handle. Pulled back to 3,470'. Work pipe until additional air compressors arrive. Well increased water rate to 54 Bbls/hr for 2-1/2 hour interval. Stabilized @ 14 Bbls/hr. Pulled back to 7" casing and test well. Flow test through 3/4" choke. 15 min. - 20 psi, 30 min. - 19 psi and stayed @ 19 psi for the remainder of the hour. One hour shut-in pressure - 300 psi. Open well, blew on its own. Rig up additional air compressors. RIH, tagged fill @ 3,485'. Cleaned out with air to 3,500'. Air rate - 3,200 cfm. (AMM)

Rig time: Blow well - 16:00

Rig up two additional air compressors - 2:30

Trip out into casing - :30

Trip to bottom - :15

Test well shut-in pressure at 300 psi - 4:15

Gauge well - :30

#### September 4, 1989

TD: 3,600' K.B.

Current Operation: Work tight hole.

Blow well through interval of 3,470' - 3,500'. Pull into 7" casing and test well. Flow through 3/4" choke. 15 min - 32 psi, 30 min - 30 psi. Stayed @ 30 psi for remainder of the hour test. One hour shut-in - 425 psi. Bled well off. RIH to 3,470' - 3,500'. Blow well. Water rate: 24 Bbls/hr. Slowed to 14 Bbl/hr. Cleaned out fill to 3,530'. Blew well one hour. Pulled into 7" casing and test well. flow test 3/4" choke. 15 min. - 30 psi. 30 min. - 35 psi. Stayed @ 35 psi for remainder of the hour. One hour shut-in - 450 psi. Bled well off. RIH, tagged fill @ 3,500'. Cleaned out to 3,530'.

Rig time: Blow well with air - 9:30

Gauge well - 3:30

Total trip time - 5:45

LD 120' pipe and blow well - 1:00 Work tight hole - 3,240' ft - 4:15

## September 5, 1989

TD: 3,600' K.B.

Current Operation: Working pipe to bottom.

Clean out to 3,600'. Hole became tight. Pulled to 3,470'. Blew well with air @ 3,200 MCF for 1-1/2 hours. Hole started getting tight. Pulled one joint and pipe became stuck. Worked pipe and

# CONFIDENTIAL

#### FEDERAL 32-8-26 No. 1

rigged up Homco Wireline. Backed off @ 3,155'. POH. Picked up fishing tools. RIH and screwed on to fish. Worked bumper sub and worked pipe free. Broke circulation with water. Pulled into 7" casing and circulated hole clean. POH w/ fishing tools. RIH, tagged fill @ 3,400'. Could not circulate. Pulled into 7" casing and broke circulation. Washed down to approximately 3,475'.

Rig time: Work stuck pipe - 9:00

Rig up Homco, run free point - 2:00

TIH, back off - :30

TOH w/ Drill pipe and 4 collars - 1:15

Hook up jars and TIH - 3:15

Drive fish free - :30

Pull one stand and circulate - 1:45

TOH for fish - 1:30

Lay 4 collars and fishing tool down - :45

TIH - 1:15

Working pipe to bottom - 12 jts off bottom - 2:15

# September 6, 1989 - Day No. 9

TD: 3,600' K.B.

Current Operation: Wash pipe to bottom. Bit # 5 - 6-1/4" Ser.

8335. Mud vis: 43, Mud wt.: 8.9.

Rig time: Work pipe to bottom - 5:30

Pull bit into intermediate casing - :30

WO mud - 2:00 Mud up - 3:45

TFB #5 - 1:45

TIH, circulate, trip gas - 1:30

Wash to bottom - 9:00

### September 7, 1989 - Day No. 13

TD: 3,600' K.B.

Current Operation: TIH w/ 5-1/2" liner with D.P. Rig time: Wash pipe from 3,279' to 3,600' - 9:00

Circulate - 5:00

Short trip, wash to bottom - 4:30

Strap out of hole - change rams - 2:30

Rig up San Juan, run 12 jts 5-1/2" csg. - 2:00 Pick up liner, rig down San Juan, TIH - 1:15

#### September 8, 1989 - Day No. 14

TD: 3,600' K.B.

Current Operation: Rigging down.

Wash 5-1/2" liner to TD @ 3,600'. Set liner. Circulate hole clean with fresh water. Pack off liner. Pull out of hole laying down DP. Drop ball (to seal off flats). Pressure test casing. Lay down drill collars. Rig down surface equipment.

Rig time: Pick up liner and TIH - :45

Tag bridge @ 3,279' and wash to bottom - 4:15

#### FEDERAL 32-8-26 No. 1

Back off liner. Circulate H<sub>2</sub>O clear - 1:30

LDDP - 2:00

Pressure test casing - :30

Trip DC in hole - 1:00

LDDC - 1:00

Rig down - 13:00

<u>ITEM</u>	<u>LENGTH</u>	DEPTH SET
Float shoe w/ sawtooth collar 12 jts. 5-1/2" 23# N-80 w/ TDC	1.80 507.81	3597'
Brown CMS hanger packer w/ packoff Top of liner Shoe and sawtooth collar	8.12	3081.27' 3081.27' 3597'

## September 9, 1989 - Day No. 15

TD: 3,600' K.B.

Current Operation: Idle

Rig time: Nipple down completion equipment - 2:00

Rigging down - 8:00 Rig idle - 14:00

Rig released @ 8:00 a.m. (Fri)

#### September 12, 1989

TD: 3,600' K.B.

Current Operation: Shut-in, preparing to log and perforate 5-1/2" liner. (SSD)

## September 13, 1989

TD: 3,600' K.B.

Current Operation: W.S.I. delivered and installed 6" x 5,000 psi frac valve. Rigged up Schlumberger and ran Compensated Neutron Gamma Ray log from 3,590' K.B. PBTD up to 3,090' K.B. Liner top logged @ 3,096' K.B. and perforated as follows per cased hole log: All - 4 shots/ft. 3,551' - 61' K.B., 3,470' - 3,500' K.B., 3,397' - 3,407' K.B., 3,366' - 76' K.B., 3,344' - 54' K.B., 3,240' - 65' K.B. Well flowing a little. SWI. (CCM)

# September 14, 1989

TD: 3,700' K.B.

Current Operation: Shut-in. Waiting on surface equipment. Tubing pressure: 900 psi. Casing pressure: 675 psi. (AMM)

# September 15, 1989

TD: 3,600' K.B.

Current Operation: Set anchors. Move Big A on location. Rig up unit. Nipple down 6" frac valve, nipple up BOP, rig up floor, tally and pickup 104 jts 2-7/8" EUE. Land tubing at top perf. Nipple down BOP, Nipple up wellhead, rig up to swab and rig up flow line. Well surging. Leave well open to pit. SDON.