

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
Southland Royalty Company

3. Address & Phone No. of Operator
Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec, T, R, M.
1795'N, 1715'E Sec.13, T-31-N, R-12W, NMPM

5. Lease Number
SF-078115

6. If Indian, All.or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number
Grenier #105

9. API Well No.

10. Field and Pool
Basin Fruitland Coal

11. County and State
San Juan County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent

☐ Abandonment

☐ Change of Plans

☐ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment

☐ Plugging Back

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut Off

☐ Altering Casing

☐ Conversion to Injection

☐ Other

13. Describe Proposed or Completed Operations

Please rescind our application for permit to drill for this well.

RECEIVED

MAY 25 1990

OIL CON. DIV.
DIST. 3

RECEIVED
BUREAU OF LAND MANAGEMENT
FARMINGTON, NEW MEXICO
MAY 16 1990
5:03 PM

ABANDONED LOCATION

14. I hereby certify that the foregoing is true and correct
Signed Peggy Madhala Title Regulatory Affairs Date 05-16-90

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITION OF APPROVAL, IF ANY:

Sm



LTR



Job separation sheet

SF-078115 (WC)
3162.3-1.0 (019)

JUN. 13 1990

CERTIFIED MAIL
P 565 392 520

Southland Royalty Company
P. O. Box 4289
Farmington, NM 87499

RECEIVED
JUN 15 1990
OIL CON. DIV.
1507.3

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 105 Grenier, SW/4NE/4, sec. 13, T. ~~33 N.~~ R. ~~12 W.~~, San Juan County, New Mexico, lease SF-078115. As requested by your Sundry Notice dated May 16, 1990, the subject APD is rescinded and returned.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

Ken Townsend

John L. Keller, Chief
FOR Branch of Mineral Resources

Enclosure

cc: New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM
87410

Well file
3162.3-1.0
ADO - 015
Suspense - FSM
Carto
Adjudication
019:SMason:sjl:6-8-90

June 1, 1960

RECEIVED
JUN 2 1960
OIL CON. DIV.
/BUREAU

The following information was received from the Bureau of Land Management, U.S. Department of the Interior, on June 1, 1960:

On June 1, 1960, the Bureau of Land Management, U.S. Department of the Interior, advised that the following information was received from the Bureau of Land Management, U.S. Department of the Interior, on June 1, 1960:

Ken Townsend

100

U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT