

F

30-045-27984

07-09-90

F. Loc. 1185/N; 1290/E Elev. 6078 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. _____ Cu. ft. _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. I. _____ @ _____ T Gas
 Csg. Perf. _____ Prod. Stim. _____

T
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas _____
 MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS	NiTD	X	Well Log	TEST DATA							Ref.No.
Ojo Alamo	C-103		Plat	Schd.	PC	Q	PW	PD	D		
Kirtland	C-104		Electric Log								
Fruitland			C-122								
Pictured Cliffs	Ditr		Dfa								
Chacra	Datr		Dac								
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
	E/324.30 Acres										

P
o
o
BasinFrCoalCo. SJ S 20 T 31N R 10W U A Oper. Koch Exploration Co. Lse. Lambe C

No. 5

Lambe C #5

A-20-31N-10W

KOCH EXPLORATION CO.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401

TAKE
PRIDE IN
AMERICA

IN REPLY REFER TO:

NM-014110 et al. (WC)
3162.3-1 (019)

RECEIVED
OCT 4 1991
OIL CON. DIV.
DIST. 3

OCT. 03 1991

Koch Exploration Company
3605 N. Dustin
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

1. 5-C Walker, sec. 13, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-014110.
2. 4-C Walker, sec. 10, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-014110.
3. 5-C Lambe, sec. 20, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-03187.

As discussed with Delvin Echard of your company on, September 26, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

Enclosures

cc:

~~Mineral Resources Conservation Division~~, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONED LOCATION