





# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
Farmington Resource Area  
1235 Laplata Highway  
Farmington, New Mexico 87401

TAKE  
PRIDE IN  
AMERICA

IN REPLY REFER TO:

NM-014110 et al. (WC)  
3162.3-1 (019)

**RECEIVED**  
OCT 4 1991  
OIL CON. DIV.  
DIST. 3

OCT. 03 1991

Koch Exploration Company  
3605 N. Dustin  
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

1. 5-C Walker, sec. 13, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-014110.
2. 4-C Walker, sec. 10, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-014110.
3. 5-C Lambe, sec. 20, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-03187.

As discussed with Delvin Echard of your company on, September 26, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller  
Chief, Branch of Mineral Resources

Enclosures

cc:

~~New Mexico Oil Conservation Division~~, 1000 Rio Brazos Rd., Aztec, NM 87410

## ABANDONED LOCATION