

F

30--045-27986

07-09-90

F. Loc. 1115/N; 1130/E Elev. 6563 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. _____ Cu. ft. _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ (e) _____ W _____ Sx. T. _____ @ _____ Gas
 Csg. Perf. _____ Prod. Stim. _____

I.P. _____		BO/D _____		MCF/D After _____		Hrs. _____		SICP _____		PSI After _____		Days GOR _____		Grav. _____		1st Del. Gas _____		TRANS
														1st Del. Oil _____				
TOPS		NiTD <u>X</u>		Well Log		TEST DATA												
						Schd.	PC	Q	PW	PD	D	Ref. No.						
Ojo Alamo		C-103		Plat <u>X</u>														
Kirtland		C-104		Electric Log														
Fruitland				C-122														
Pictured Cliffs		Ditr		Dfo														
Chacra		Datr		Dac														
Cliff House																		
Menefee																		
Point Lookout																		
Mancos																		
Gallup																		
Greenhorn																		
Dakota																		
Entrada																		

E/277.56
Acres

P
o
o
BasinFrCoalCo. SJ S 13 T31N R10W U A Oper. Koch Exploration Co. Lse. Walker C

No. 5

Walker C #5

A-13-31N-10W

KOCH EXPLORATION CO.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



IN REPLY REFER TO:

NM-014110 et al. (WC)
3162.3-1 (019)

RECEIVED
OCT 4 1991
OIL CON. DIV.
DIST. 3

OCT. 03 1991

Koch Exploration Company
3605 N. Dustin
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

1. 5-C Walker, sec. 13, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-014110.
2. 4-C Walker, sec. 10, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-014110.
3. 5-C Lambe, sec. 20, T. 31 N., R. 10 W., San Juan Co., NM, lease NM-03187.

As discussed with Delvin Echard of your company on, September 26, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

Enclosures

cc:

~~New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410~~

ABANDONED LOCATION