

F


30-045-28032

07-31-90

F. Loc. 2500/N; 1010/E Elev. 6811 GL Spd. \_\_\_\_\_ Comp. \_\_\_\_\_ TD \_\_\_\_\_ PB \_\_\_\_\_  
 Cu. ft. Cu. ft. Cu. ft.  
 Casing S. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Int. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Pr. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. T. \_\_\_\_\_ @ \_\_\_\_\_  
 Csg. Perf. \_\_\_\_\_ Prod. Stim. \_\_\_\_\_

T  
R  
A  
N  
S

BO/D \_\_\_\_\_ Grav. \_\_\_\_\_ 1st Del. Gas  
 I.P. \_\_\_\_\_ MCF/D After \_\_\_\_\_ Hrs. SICP \_\_\_\_\_ PSI After \_\_\_\_\_ Days GOR \_\_\_\_\_ 1st Del. Oil

TOPS		NiTD	X	Well Log	TEST DATA									
Ojo Alamo		C - 103	✓✓	Plot	X	Schd.	PC	Q	PW	PD	D	Ref.No.		
Kirtland		C - 104		Electric Log										
Fruitland				C - 122										
Pictured Cliffs		Ditr		Dfa										
Chacra		Datr		Dac										
Cliff House														
Menefee														
Point Lookout														
Mancos														
Gallup														
Greenhorn														
Dakota														
Entrada														
		E/316.71 Acres												

P  
o  
o

BasinFrCoal Co. SJ S 21 T 32N R 09W UH Oper. Meridian Oil Inc. Loc. San Juan 32-9 Unit No. 272

San Juan 32-9 Unit #272

H-21-32N-09W

MERIDIAN OIL INC.

NM SF-079341 (WC)  
3162.3-1.0 (019)

OCT. 01 1992

**RECEIVED**  
OCT 05 1992  
OIL CON. DIV.  
DIST. 3

Ms. Peggy Bradfield  
Meridian Oil Incorporated  
P. O. Box 4289  
Farmington, NM 87499

Dear Ms. Bradfield:

Reference is made to your Application for Permit to Drill (APD) Well No. 272 San Juan 32-9 Unit, 2500' FNL/1010' FEL in the SE $\frac{1}{4}$ NE $\frac{1}{4}$  SEC. 21, T. 32 N., R. 09 W., San Juan County, New Mexico, Federal lease NM SF 079341. As we have received no report of drilling operations commencing prior to expiration, the subject APD has expired, as of July 27, 1992, and is returned. Please note that it is the policy of this office to grant extensions of APDs up to a total of one year from the original expiration date. Any expired APD may be resubmitted at any time when more definite drilling plans are formulated.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller  
Chief, Branch of Mineral Resources

Enclosure

cc:  
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

**ABANDONED LOCATIONS**