GREAT WESTERN DRILLING CO.

| F | | | | 30-045-28495 | | | 01-04-91 | | | | | | |
|---------------------|---|--------------------|----------------------|----------------------------|----------------------------------|-------|--|----------|-------------------|----|-------------|--------|--|
| F.l∝ 895/S; 840/W | | | | Elev6085_GLSpd | | | CompP8 | | | | | | |
| asing S sg.Perf. | w | Cu. ft. Sx. Int | @ | w | Cu. ft. Sx. Pr Prod. Stim. | | | w | Cu. ft. \$x. T | · | -@ | T Gas | |
| BO/D PHrs. SICP | | | PSI | Grav PSI After Days GOR | | | 1st Del. <u>Gas</u> 1st Del. <u>Oil</u> | | | | N S | | |
| TOPS | | NITD | X Well Log TEST DATA | | | | | | | | | | |
| Ojo Alamo | | C - 103 | | Plat | X | Schd. | PC | Q | PW | PD | D | Ref.No | |
| Kirtlano | | C - 104 | | Electric Log | 1 | | | | | | | | |
| Fruitland | | | | C-122 | | | | | | | | | |
| Pictured Cliffs | | Ditr | ' | Dfa | | | | | | | | | |
| Chacra | | Datr | | Dac | | | | <u> </u> | | | | | |
| Cliff House | | | | | | | | | | | | | |
| Menefee | | 1 | | | | | | | | | | | |
| Point Lookout | | 1 | | | | | | | | | | | |
| Mancos | | | | | | | | | | | | 1 | |
| Gallup | | | | | | | | | | | | | |
| Greenhorn | | | | | | | | | | | | | |
| Dakota | | | | | | | | | 1 | | | | |
| Entrada | | 1 | | | | | | | 1 | | | | |
| | | 1 | | | Acres W/320 | | | | | | | | |
|)) | | <u> </u> | | | | | | | | | | | |



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Farmington Resource Area 1235 Laplata Highway Farmington, New Mexico 87401



IN REPLY REFER TO: SF-078096 (WC) 3162.3-1 (019)

OCT. OB 1991

OCT. 9 1991

OIL CON. DIV

Great Western Drilling Company 2550 La Plata Hwy. Farmington, NM 87401

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 60 Mudge "C", SW/4 sec. 9, T. 31 N., R. 11 W., San Juan County, New Mexico, lease SF-078096. As per your Sundry Notice received October 3, 1991, the subject APD is rescinded and returned.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

Isl John L. Keller

John L. Keller Chief, Branch of Mineral Resources

Enclosure

cc:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONED LOCATION