Form 3160-5	UNITED STATES		FORM APPROVED
DEPARTMENT OF		F THE INTERIOR	BUDGET BUREAUNO. 1004-0135
BUREAU OF LAND MANAGEMENT			EXPIRES: MARCH 31, 1993
	201121001211	RECEIVED	5. Lease Designation and Serial No.
	SUNDRY NOTICE	ES AND REPORTS ON WELLS	NM83503
Do not use this form for propo	sals to drill or to de	enen or reentry to a	
different reservoir Use "APPI	ICATION FOR PE	RMIT - " for-such proposals: \ \	6. If Indian, Allottee or Tribe Name
<u> </u>	SUBMIT IN TRIPL	ICATE	
1. Type of Well	OODIVIIT IIA TIXIFE		7 16110% 00 00 00000000000000000000000000
[] Oil Well [X] Gas Well	[] Other	070 FrankAGTON, NM	7. If Unit or CA, Agreement Designation
2. Name of Operator	[] Onlet	010 17 % 17.11 (201 0 . 1)	
CNG Producing Company			8. Well Name and No.
3. Address and Telephone No	Grassy Canyon #2 (CNG #3953)		
	9. API Well No.		
CNG Tower - 1450 Poydra	30-045-70237-90 28560		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			10. Field and Pool, or Exploratory Area
624' FSL & 507' FML of Sec. 30-T32N-R7W			Basin Fruitland Coal
3			11. County or Parish, State
			San Juan, New Mexico
CHECK APPRO	OPRIATE BOX(S) 1	TO INDICATE NATURE OF NOTIC	
TYPE OF SUBI			E OF ACTION
[] Notice of Inte	ent	[] Abandonment	[] Change of Plans
		[] Recompletion	[] New Construction
[X] Subsequent	Report	[] Plugging Back	[] Non-Routine Fracturing
		[] Casing Repair	[] Water Shut-Off
[] Final Abandonment Notice		[] Altering Casing	[] Conversion to Injection
		[x] Other - Summary of Operation	ns [] Dispose Water
			(Note: Report results of multiple
			completion on Well Completion or
			Recompletion Report and Log form.)
blades) and HI torque moderal up 1.690" mill, tag at blades). UR open coal in UR blades with motor on and UR in hole. Rig down began flowing up tubing. Run in hole with 5 stands at 250 MCF/D.	ng equipment and reptor on 1 1/4" coil tu 3,515'. Wash out of aterval from 3,535' - coil tubing from 3,5 n coil equipment. Foam water and so . Well flowing up tu	eturns to tank. Test all equipment. bing. Tag at 3,515'. Unable to ma coal fill with pilot hole to 3,535'. Pu 3,580'. Pull out of hole. Washing 30' - 3,620' with foam. Lost 1,000 Rig up rig. Nipple up BOP. Pull out mall amount of coal. Shut in tubing bing. Pump 10 bbls. Land hange	Run in hole with 1.690" UR (4 1/2" OD ke hole. Pull out of hole. Lay down UR. Il out of hole. Pick up 1.690" UR (3 1/2" out coal bed (open hole) with 4.55" OD PSI. Pull out of hole. Left 90' of coil, motor of hole with 5 stands 2 7/8" tubing. Well Bullhead 10 bbls hot water down tubing. Nipple up tree. Swab well on production
(This space for Federal or		•	
Approved by Title Date			ate
Conditions of approval, if a			
Title 18 U.S.C. Section 1001, agency of the United States ar within its jurisdiction.	makes it a crime for ny false, fictitious or	any person knowingly and willfully fraudulent statements or represen	to make to any department or tations as to any matter
Within its jurisdiction.	*See	Instructions on Reverse	Side ACCEPTED FOR RECORD
可国の日間			
DEGEIV Nov - 3 153	NEW		NOV 01 1005
	中国		NOV 01 1995
- NOV - 3 193	5 U	NMOO	
OUL GOM. DIV.		,-mu-000	FARMINGTON DISTRICT OFFICE
= Elevato E	ンローム		

OUL COM. DIV.