UNITED STATES

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

BLM

Sundry Notices and Reports of the lis	110:17	
070 FARMINGT	ON, NM 5.	Lease Number SF-078509
1. Type of Well GAS	6.	If Indian, All. or Tribe Name
2. Name of Operator	7.	Unit Agreement Name San Juan 32-9 Unit
MERIDIAN OIL  3. Address & Phone No. of Operator	8.	Well Name & Number San Juan 32-9 U #41A
PO Box 4289, Farmington, NM 87499 (505) 326-9700	- '	API Well No. 30-045-29129 . Field and Pool
4. Location of Well, Footage, Sec., T, R, M 815'FSL, 1120'FEL, Sec.31, T-32-N, R-9-W, NMPM		Blanco Pict.Cliffs Ext Blanco Mesaverde
		. County and State San Juan Co, NM
X Subsequent Report Plugging Back Casing Repair W Casing Repair Altering Casing Casing Completed Operations  7-14-94 RU. Ran CBL-CCL-GR @ 0-6230', TOC @ 3434'. 7-19-94 TIH w/7" FB pkr, set @ 3198'. Pump 500 sx Casing Repair W Casing Repair W Casing	Jater Shut onversion	off to Injection 
3 pps Gilsonite, 0.25 pps Flocele, 2% cal Tailed w/100 sx Class "B" Neat w/2% calci 7-20-94 Drill cmt @ 3253-3425'. Circ hole clean. PT min, OK. TOOH. RU, Ran CBL @ 0-3532', TOC	cium chloridon chloridon chloridon 7" csg, s	ide (885 cu.ft.). e (118 cu.ft.). WOC qz to 1000 psi/15 D.
		EGEIVED AUG 1 7 1994
		IL CON. DIV. DIST. 3
Signed Malhu Title Regulatory Affair		8/9/94
(This space for Federal or State Office use) APPROVED BY Title	Date	
CONDITION OF APPROVAL, if any:	(CO)	EPTED FOR RECORD
		ынд 1 н <b>1994</b>

FARMINGTON DISTRICT OFFICE BY Son