OIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

February 19, 1963

Mr. W. H. Williams Consolidated Oil & Gas, Inc. Writer Building, 4150 East Mexico Ave. Denver 22, Colorado

> Re: Packer-Leakage Test, #1-35 Montoya, H-35-32N-13W

Dear Mr. Williams:

The enclosed graph of relative pressures of subject test indicates that the build-up rate of the Dakota formation may have suffered interference during the Mesaverde flow period.

Please re-schedule the first half of the packer-leakage test to be submitted as supplemental information to the report received in this office February 18, 1963. (Both zones to be shut in for one week, then flow the Mesaverde for one week while the Dakota formation remains shut in.

Yours very truly

A. R. Kendrick
Engineer, District #3

ARK: ks

Encl.

OIL CONFERVATION DESCRIPTION

tada serate dis ucer Solau westants .

i este per el como de la composición d La composición de la

ుకుండింది. అన్నుకుండి కొర్పుడు ఎక్కువడు కొర్పుకుంటి ఎక్కువడి మేరుకుండి. కొనువుకుండి ఆయోగ తూడా ప్రాణం కొర్పుడు కొర్పుడు కొర్పుడు కొర్పుడుకోవుడు. కొర్పుడుకోవుడుకోవిడుకోవిడు కొర్పుడుకోవిడు కారంకుండు ఎళ్ళి ప్రాణంకి కొర్పుడుకోవిడుకోవిడుకోవిడుకోవిడుకోవిడుకోవిడుకోవిడుకోవిడుకోవిడుకోవిడుకోవిడుకోవిడుకోవి

A Section of the second of the

Subman**s**Sill. District States and Siller

COSTALE.

44.00