submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Sundry Notices and Reports on Wells

57	1	-(,	:::	.:]

	UIU THERE I THE CONTRACTOR
	5. Lease Number
	14-20-603-5012
1. Type of Well	6. If Indian, All. or
Oil . , /	Tribe Name
Harrison Let.	Navajo
Harrison fel.	7. Unit Agreement Name
2. Name of Operator	N/A
Texas Pacific Oil & Gas Co., C/O Joseph E. Seagram & Sons, Inc.	
	8. Well Name & Number
3. Address & Phone No. of Operator	Navajo #3X
800 3rd Ave., New York City, NY 10022-7699	9. API Well No.
·	30-045-1123300
4. Location of Well, Footage, Sec., T, R, M	10. Field and Pool
625' FSL and 2000' FEL Sec.27 , T-32-N, R-17-W, NMPM	Many Rocks
0	11. County & State
	San Juan County, NM
	,,
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTIC	CE. REPORT. OTHER DATA
Type of Submission Type of Action	
	inge of Plans
	v Construction
	n-Routine Fracturing
	er Shut off
	version to Injection
Other -	version to injustion
Other -	
13. Describe Proposed or Completed Operations	
13. Describe Proposed of Completed Operations	
· · · · · · · · · · · · · · · · · · ·	
To the Otto Octoor of and shandaned	this well as March OC 4007
Texas Pacific Oil & Gas Co., plugged and abandoned	this well on March 26, 1997
per the attached Plug & Abandonment report.	
الالا	?@Enga-
빈	GEIWIAR
AF	*R - 8 1997 <i>[Y</i>]
14. I hereby certify that the foregoing is true and correct.	COM Dag
	COM, DIV.
Signed Malliam + Cart Title Contra	ctor型。
William F. Clark, President A-Plus Well Service	
(This space for Federal or State Office use)	
APPROVED BY Sech Title Fac & ng co	nee Date Arriv
CONDITION OF APPROVAL, if any:	

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211

Texas Pacific Oil & Gas Co., c/o Joseph E. Seagram & Sons Navajo #3 X 625' FSL and 2000' FEL, Sec. 27, T-32-N, R-17-W, San Juan County, NM BIA 14-20-603-5012

April 2, 1997

Plug & Abandonment Report

Cementing Summary:

Plug #1 with 62 sxs Class B cement from 1740' to 1095' to fill Gallup perforations and cover top.

Plug #2 with 95 sxs Class B cement pumped down 5" casing from 353' to surface, cover Mesaverde top; and circulate good cement to surface out 8-5/8" annulus.

Plugging Summary:

Notified BLM on 3/25/97

- 3-25-97 Road rig to location. RU rig and equipment. Open up well, no pressures. PU on tubing and break off wellhead. Strip on wellhead and NU BOP. RU rig floor. Work tubing to release packer then POH with 4-1/2" Model "A" packer and 55 joints tubing, 1705'. PU plugging sub and RIH to 1405'. Shut in well. SDFD.
- 3-26-97 Safety Meeting. Open up well, no pressures. Continue to RIH with tubing and tag bottom at 1740'. Establish circulation with 12 bbls water. Plug #1 with 62 sxs Class B cement from 1740' to 1095' to fill Gallup perforations and cover top. POH to 500' and WOC. Open up well and RIH; tag cement at 1207'. Load casing with water and pressure test to 300# for 10 min, held OK. POH and LD tubing. RU A-Plus wireline truck and RIH. Perforate 2 squeeze holes at 353'. Establish circulation down 5" and out 8-5/8" with 10 bbls water. Plug #2 with 95 sxs Class B cement pumped down 5" casing from 353' to surface, cover Mesaverde top; and circulate good cement to surface out 8-5/8" annulus. ND BOP and wellhead. Cut wellhead off; found cement down 15' in 5" and 8-5/8" annulus. Mix 35 sxs Class B cement, fill casing and annulus; then install P&A marker. RD rig and equipment; prepare to move off location.

 J. Sanchez, BLM representative was on location.