UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

		5.	Lease Number
Town of Woll		6.	14-20-603-5012 If Indian, All. or
. Type of Well Oil		0.	Tribe Name
	7 4		Navajo
Harrison 4	iet	7.	Unit Agreement Name
Name of Operator	ms & Sons Inc		N/A
Texas Pacific Oil & Gas Co., C/O Joseph E. Seagrar	ins & Johs, inc.	8.	Well Name & Number
Address & Phone No. of Operator		-	Navajo #11
800 3 rd Ave., New York City, NY 10022-7699		9. 🥿	API Well No.
CM-II France Con T. D. M.		ري م	-045-(1295-
Location of Well, Footage, Sec., T, R, M 1360' FNL and 260' FWL Sec.27, T-32-N, R-17-W, N	IMPM	10.	Many Rocks
E	1411 141		Wally Hooks
P		11.	County & State
			San Juan County, NM
. CHECK APPROPRIATE BOX TO INDICATE NATI	TIRE OF NOTICE BEDOD	OTHER	PDATA
Type of Submission Type of Action	ONE OF NOTICE, NET ON	i, Oiliei	CDAIA
X_ Notice of Intent _X_Abandonment	Change of Plans		
Recompletion	New Construction		
Subsequent ReportPlugging Back	Non-Routine Fractur	ing	
Casing Repair	Water Shut off	20	
Final AbandonmentAltering Casing Other -	Conversion to Injection	ווכ	
Describe Proposed or Completed Operations			
. Describe Proposed or Completed Operations Texas Pacific Oil and Gas Co., proposes to Plug procedure and diagram.	and Abandon this well per th	e attached	S: 1
Texas Pacific Oil and Gas Co., proposes to Plug	and Abandon this well per th	e attached	77 TEN
Texas Pacific Oil and Gas Co., proposes to Plug	and Abandon this well per th	e attached	<u> </u>
Texas Pacific Oil and Gas Co., proposes to Plug	and Abandon this well per th	e attached	7 FEB 25
Texas Pacific Oil and Gas Co., proposes to Plug		e attached	7 FEB 25 (C)
Texas Pacific Oil and Gas Co., proposes to Plug		e attached	7 FEB 25
Texas Pacific Oil and Gas Co., proposes to Plug		e attached	7 FEB 25 (C)
Texas Pacific Oil and Gas Co., proposes to Plug	MAR - 3 MAY DIVINOR DELETA	e attached	775825 CO 0: 1
Texas Pacific Oil and Gas Co., proposes to Plug		e attached	775825 (II 0: 1
Texas Pacific Oil and Gas Co., proposes to Plug procedure and diagram.	MAR - 3 MAY DIVING CORP. 18	e attached	77720 25 (C) 0: 1
Texas Pacific Oil and Gas Co., proposes to Plug procedure and diagram.	MAR - 3 MAY DIVING CORP. 18	e attached	77720 25 (C) 0: 1
Texas Pacific Oil and Gas Co., proposes to Plug procedure and diagram. I hereby certify that the foregoing is true and corrections.	1000 1000 1000 1000 1000 1000 1000 100		7728 25 EE 0: 16
Texas Pacific Oil and Gas Co., proposes to Plug procedure and diagram. I hereby certify that the foregoing is true and corrected with the source of the control of the con	1000 1000 1000 1000 1000 1000 1000 100	e attached	7728 25 EE 0: 16
I hereby certify that the foregoing is true and corrected William F. Clark, A-Plus Well Service	1000 1000 1000 1000 1000 1000 1000 100		7728 25 (C) 0: 16
Texas Pacific Oil and Gas Co., proposes to Plug procedure and diagram. I hereby certify that the foregoing is true and corrected with the source of the control of the con	ct.		77EB 25 (C) 0: 16

Navajo #11-27

Proposed P&A

Many Rocks Gallup

1360'N, 260'W Sec 27, T-32-N, R-17-W, San Juan County, NM

Today's Date: 2/18/97

Gallup @ 1330'

Sanostee @ 1653'

Spud: 6/5/64 Completed: 6/14/64

Point Lookout @ Surface

9-3/4" Hole

PBTD 1689

TD 1694'

7-5/8" 24# Casing Set @ 31' Cmt with 8 sxs (Circulated to Surface)

Perforate at 81'

Plug #2 81' - Surface Cmt with 18 sxs Class B.

TOC @ 1178' (Calc, 75%)

Plug #1 1640' - 1280' Cmt with 50 sxs Class B (displace to 300')

Gallup Perforations: 1634' - 1640'

2-7/8" 6.5# Csg @ 1689' Cemented with 45 sxs

Well History:

4-3/4" Hole

7-5/8" 24# surface csg set at 31' cemented to surface with 7 sxs

2-7/8" 6.5# csg set at 1689' with 45 sxs

Gallup zone perforated 1634' - 1640' with 4 SPF.

No rods, tubing or equipment on location.

Water injection well.

Proposed Rigless Plugging Procedure:

- 1. Establish rate down 2-7/8" casing with 15 bbls water, if no flow or blow, drop 6 frac balls to confirm no casing leak. If bradenhead flows or there is a casing leak, then use tubing to spot cement. Plug #1 from 1640' to 1280' with 50 sxs Class B cement, displace to 300'. WOC.
- 2. RU A-Plus wireline truck. RIH and tag cement. Perforate 2 squeeze holes at 81'. Establish circulation out bradenhead. Mix and pump 18 sxs Class B cement from 81' to surface, circulate good cement out bradenhead.
- 3. WOC, cut off wellhead and install P&A marker.