(Formerly 9–331) DEPARTMENT O BUREAU OF LAI	STATES SUBMIT IN TRIPLICA (Other instructions of verse side) ND MANAGEMENT	Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. I-22-IND-2772 6. IF INDIAN, ALLOTTER OR TRIBE NAME
SUNDRY NOTICES AN (Do not use this form for proposals to drill Use "APPLICATION FOR	ND REPORTS ON WELLS or to deepen or plug back to a different reservoir. PERMIT—" for such proposals.)	Ute Indian 7. UNIT AGREEMENT NAME
OIL GAS X OTHER .		
2. NAME OF OPERATOR		8. FARM OR LEASE NAME Ute
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR		9. WBLL NO.
P.O. Box 4289, Farmington,	New Mexico 87499-4289	#11
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)		10. FIELD AND POOL, OR WILDGAT
2310'N, 2310'W		Barker Creek Paradox 11. EBC., T., E., M., OR BLE. AND SURVEY OR ARMA NMPM
		Sec. 21, T32N, R14W
14. PERSIT NO. 15. BLEVAT	6637 GL	San Juan New Mex
	Box To Indicate Nature of Notice, Report,	
NOTICE OF INTENTION TO:	801	BREQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTH	<u> </u>	REPAIRING WELL ALTERING CASING
FRACTURE TREAT SHOOT OR ACIDIZE ABANDON®	SHOOTING OR ACIDIZING	
REPAIR WELL CHANGE PLAN		suits of multiple completion on Well
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Cle proposed work. If well is directionally drilled,	give subsurface incetions and measured and true ve	ates, including estimated date of scaling an
This well was reviewed and possible zones:	is in mechanical condition to r	
This well was reviewed and	is in mechanical condition to r	
This well was reviewed and possible zones: <u>Depth</u>	is in mechanical condition to r	recomplete in the following
This well was reviewed and possible zones: Depth 8320-55 Barke	is in mechanical condition to r	recomplete in the following ated Reserves (BCFG)
This well was reviewed and possible zones: Depth 8320-55 Barke 4840-55 Shine	is in mechanical condition to r Zone Estimate Creek - 1st Sour	recomplete in the following ated Reserves (BCFG) 4.48
This well was reviewed and possible zones: Depth 8320-55 Barke	is in mechanical condition to r Zone Estimate Creek - 1st Sour	ecomplete in the following ated Reserves (BCFG) 4.48 1.92
This well was reviewed and possible zones: Depth 8320-55 Barke 4840-55 Shine	is in mechanical condition to r Zone Estimate Creek - 1st Sour	recomplete in the following ated Reserves (BCFG) 4.48
This well was reviewed and possible zones: Depth 8320-55 Barke 4840-55 Shine 4840-55	is in mechanical condition to r Zone Estimate Creek - 1st Sour	ated Reserves (BCFG) 4.48 1.92 OIL CON. DIV. DIST. 3 to handle additional sour above makes it uneconomical
This well was reviewed and possible zones: Depth	Zone Estimater Creek - 1st Sour arump ty of the pipeline connection to elete and test each zone listed this time. It is requested to	ated Reserves (BCFG) 4.48 1.92 OIL CON. DIV. DIST. 3 to handle additional sour above makes it uneconomical leave this wellbore in its
This well was reviewed and possible zones: Depth	Zone Estimater Creek - 1st Sour arump ty of the pipeline connection to lete and test each zone listed this time. It is requested to	ated Reserves (BCFG) 4.48 1.92 OIL CON. DIV. DIST. 3 to handle additional sour above makes it uneconomical leave this wellbore in its
Depth 8320-55 4840-55 Shine 26 1985 Due to present unavailabili gas, and the cost to recompto recomplete this well at present shut-in status. 18. I hereby certify that the foregoing is true and cost of the cost of th	Zone Estimater Creek - 1st Sour arump ty of the pipeline connection to elete and test each zone listed this time. It is requested to	ated Reserves (BCFG) 4.48 1.92 OIL CON. DIV. DIST. 3 to handle additional sour above makes it uneconomical leave this wellbore in its
Depth 8320-55 4840-55 Shine 26 1985 Due to present unavailabili gas, and the cost to recomp to recomplete this well at present shut-in status. 18. I hereby certify that the foregoing is true and cost in status. (This space for Federal or State office use) APPROVED BY APPROVED BY LEANT AND THE OFFICE USE)	Zone Estimater Creek - 1st Sour arump ty of the pipeline connection to elete and test each zone listed this time. It is requested to	ated Reserves (BCFG) 4.48 1.92 OCTUB 1985 OIL CON. DIV. DIST. 3 to handle additional sour above makes it uneconomical leave this wellbore in its DATE September 24. 1

reeu oi

NOT TO EXCEED 1 YEAR.

*See Instructions on Reverse Side