
Form 9-331 a (Feb. 1951)



## (SUBMIT IN TRIPLICATE)

## UNITED STATES **DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY**

Land Office	Santa f	3	-
Lease No.	5 <b>F07881</b> 8	-	_
Unit SI/	h, NE/h,	Sea	22
	R-13W,		

NOTICE OF IN	·				
	TENTION TO DRILL	s	UBSEQUENT REPOR	RT OF WATER SHUT-OFF	XX
	TENTION TO CHANGE PLAN		•	RT OF SHOOTING OR ACIDIZING	İ
NOTICE OF IN	TENTION TO TEST WATER S	SHUT-OFF S	UBSEQUENT REPOR	RT OF ALTERING CASING	
NOTICE OF IN	TENTION TO RE-DRILL OR	REPAIR WELL S	UBSEQUENT REPOR	RT OF RE-DRILLING OR REPAIR	
NOTICE OF IN	TENTION TO SHOOT OR AC	IDIZES	UBSEQUENT REPOR	RT OF ABANDONMENT	
NOTICE OF IN	TENTION TO PULL OR ALTE	R CASING S	UPPLEMENTARY W	ELL HISTORY	XX
NOTICE OF IN	TENTION TO ABANDON WEL	<b>L</b>		·	
	(INDICATE A	BOVE BY CHECK MARK NATUR	E OF REPORT, NOTI	CE, OR OTHER DATA)	
				February 19	, 1960
3£/4	1 Jones is located	1940 ft. from [N] 32N 13 (Twp.) (Range)	W H	ft. from E line	of sec. 22
0		San Juan		Men Mexic	80
ATTA	(Field)	(County or Subdiv	vision)	(State or Territory	X.X
		ing points, and all other im	hts, and lengths of portant proposed		
1. Ser cas 2. Pri on 3. Ges	99 joints, 7- sing at 3.25' R. illed plug and p February h, 190 s drilled hole	jective sands; show sizes, weig ing points, and all other im 5/6", 3-55, 26.40 A.B. Cemented w pressured up on 50 - Pressure hel	hts, and lengths of portant proposed of the casing of 7-5/5" casid	n February 2, 1966 ualar w/2% gel. ing to 600 pai for hole on February 1	0 - Landed r 30 adns.
1. Sar can 2. Dri on 3. Can Enc Pli I understand	99 joints, 7-sing at 3425 R. Illed plug and property is, 196 drilled hole frounted water ag & Abandone.	jective sands; show sizes, weiging points, and all other im  5/0", J-55, 26.40  K.B. Cemented works are on the control of the	hts, and lengths of portant proposed of the casing of the case of	original signe 1 in	o - Landed r 30 mins. 16, 1980. ant to
1. Sar cas 2. Dri on 3. Cas Enc Pli I understand	a 99 joints, 7-5 sing at 3425' R. illed plug and g Pebruary h, 196 s drilled hole t counteded water ag & Abandone.  d that this plan of work many 30UTHAR; UNI P. O. Box 5	jective sands; show sizes, weiging points, and all other im  5/0", J-55, 26.40  K.B. Cemented works are up on  50 - Pressure helt  to T.D. of 5670 -  at T.D. 5670 in	hts, and lengths of portant proposed of the casing of the	original signed by VERNON J. LOW	o - Landed r 30 mins. 16, 1980. ant to
1. Sar cas 2. Dri on 3. Cas Enc Pli I understand	99 joints, 7-sing at 3425 R. Illed plug and property is, 196 drilled hole frounted water ag & Abandone.	jective sands; show sizes, weiging points, and all other im  5/0", J-55, 26.40  K.B. Cemented works are up on  50 - Pressure helt  to T.D. of 5670 -  at T.D. 5670 in	hts, and lengths of portant proposed of the casing of the	original signe 1 in	o - Landed r 30 sdns. 16, 1980. ant to

