

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. SF-081240
2. NAME OF OPERATOR Aztec Oil & Gas Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Drawer 570, Farmington, New Mexico		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1490' FSL & 790' FEL		8. FARM OR LEASE NAME Horton
14. PERMIT NO.		9. WELL NO. #1-A
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6330' GR		10. FIELD AND POOL, OR WILDCAT Blanco Mesa Verde
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 35, T32N, R11W
		12. COUNTY OR PARISH San Juan
		13. STATE New Mexico


16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Casing report</u> <input checked="" type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-6-77 Ran 80 joints of 7", 20#, K-55, 8rd casing. Total 3292.80', shoe set at 3278', insert float valve at 3235'. Cemented with 130 sacks 65/35 Class "B" with 12% gel and 70 sacks Class "B" with 2% CaCl. Plug down at 2:45 PM.

5-8-77 Ran 57 joints of 4½", 10.50#, K-55, 8rd casing. Total 2372', shoe set at 5512.9', float collar set at 5511.9', liner hanger set at 3125.92'. Cemented with 300 sacks 50/50 Poz A, Class "B" with 2% gel, 6.25# fine gilsonite per sack, ¼# gel flake per sack and 0.6% D-60. Plug down at 7:55 AM.



RECEIVED
MAY 10 1977

18. I hereby certify that the foregoing is true and correct
SIGNED [Signature] TITLE District Production Manager DATE May 9, 1977

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: