# DESIGNATION OF OPERATOR

77		•	. •						
The ii	けいいっていいりゃく	ווג הו	n the tecni	de at i	ha D	T 1	Management,		
	uncice on grant and a	. ,,, 0	n are recor	us ul li	ue nurezu or	1 204	Management	<b>Lall</b>	
							AVIANAR CHICHL.	noider c	)T 16256

DISTRICT LAND OFFICE:

Farmington, New Mexico

SERIAL NO.:

82-078146A (SF-078146A)

and hereby designates

Kimbark Operating Co. 1860 Lincoln Street #808 Denver, Colorado 80295

NAME:

ADDRESS:

as his operator and local agent, with full authority to act in his behalf in complying with the terms of the lease and regulations applicable thereto and on whom the supervisor or his representative may serve written or oral instructions in recuring compliance with the Operating Regulations with respect to (describe acreage to which this designation is applicable):

> Township 32 North, Range 12 West San Juan County, New Mexico

Section: NW/4 of 27

It is understood that this designation of operator does not relieve the lessee of responsibility for compliance with the terms of the lease and the Operating Regulations. It is also understood that this designation of operator does not constitute an assignment of any interest in the lease.

In case of default on the part of the designated operator, the lessee will make full and prompt compliance with all regulations, lease terms, or orders of the Secretary of the Interior or his representative.

The lessee agrees promptly to notify the supervisor of any change in the designated operator.

Kimbark Associates

WK aubushle BY: (Signature of lessee) Walter K. Arbuckle, General Partner 1860 Lincoln Street #808 February 8. 1978..... Denver, Colorado 80295 (Address)

## SUITE BOB LINCOLN TOWER BUILDING 1860 LINCOLN STREET

## DENVER, COLORADO 80295 303-839-8504

KIMBARK OPERATING COMPANY KIMBARK COMPANY KIMBARK ASSOCIATES

> WALTER K. ARBUCKLE GEORGE WALLACE BAYNE WILLIAM R. THURSTON

February 8, 1978

United States Department of Interior Bureau of Land Management PO Box 568 Farmington, New Mexico 87401

#### Genilemen:

The 13 Point Program for Kimbark Operating Co., Horton #4-A well is as follows:

- 1. See attached topographic map showing access from closest access road, about 1300' to NW.
- 2. Utilize existing access roads in area, new road across relatively flat terrain.
- 3. Existing producing wells are shown on attached plat. All other wells are P & A. This is a development in-fill location.
- 4. See attached topographic map
- 5. See attached plat
- 6. The water will be hauled from irrigation ditch or Animas River at Aztec, New Mexico.
- 7. All drill cutting and hand garbage will be covered over in rotary pits. All flamable material will be burned in burn pit and ashes covered over after drilling. All wire line, etc., will be hauled away.
- 8. None.
- ዓ. None.


- 10. See attached layout.
- 11. There is only sage brush, sparse grass at this location. There is no top soil, only sand. After leveling and cleanup, it is our plan to plant appropriate grass seed for this area when the moisture level is sufficient to support grass germination. Pits will be fenced till dry enough to fill. Contour of land will be affected as little as possible.
- 12. The topography here is relatively smooth. Operator will keep location as small as possible under the circumstances.
- 13. I hereby certify that I, or persons under my direct supervision, have inspected the proposed drillsite and access route; that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge, true and correct; and, that the work associated with the operations proposed herein will be performed by Kimbark Operating Co. and its contractors and sub-contractors in conformity with this plan and the terms and conditions under which it is approved.

Kimbark Operating Co.

W. K. Arbuckle, President


WK aubulle

WKA: iI



150 Ser. d30 <u>50</u>/ STEEL PIT AND Dia Bicrive 50, 300 P175 pu mp LATEINE 2'XY'NY' DEEP 8/12/x4/ Dep.

-



R12W

Location Map Kimbark Operating Co. #4A Horton NW 27-32N-12W San Juan County, New Mexico

SUITE 808 LINCOLN TOWER BUILDING 1860 LINCOLN STREET

KIMBARK OPERATING COMPANY
KIMBARK COMPANY
KIMBARK ASSOCIATES

DENVER, COLORADO 80295 303-839-8504

> WALTER K. ARBUCKLE GEORGE WALLACE BAYNE WILLIAM R. THURSTON

February 8, 1978

Well: Horton #4-A

Location: Section 27, T-32-N, R-12-W San Juan County, New Mexico

<u>Subject:</u> Safety and Resource Protection 7-Point Program

- 1) 9 5/8" 36# K-55, new
- 2) 10 3/4" 900 series, 6000 psi
- 3) None
- 4) Schaffer 10 3/4", 900 series double gate, 6000 psi
- 5) Kelly cocks available, bit float, sub and valve on floor
- 6) Anticipated BOP 400#
- 7) Water base mud

SUITE 808 LINCOLN TOWER BUILDING
1860 LINCOLN STREET
DENVER, COLORADO 80295
303-839-8804

WALTER K. ARBUCKLE SEORGE WALLACE BAYNE WILLIAM R. THURSTON

February 8, 1978

United States Geological Survey P. O. Box 959 Farmington, NM 87401

Re: Kimbark Operating Co.

#4A Horton

NW¼ Sec. 27-32N-12W

San Juan County, New Mexico

# Gentlemen:

The attached letter agreement has been submitted to the surface land owner for signature. When received, a copy will be forwarded for your records

Yours very truly

Elliott A. Riggs

Agent

EAR:je Enclosure

SUITE 608 LINCOLN TOWER BUILDING 1860 LINCOLN STREET DENVER, COLORADO 80298 303-839-8804

WALTER K. ARBUCKLE
GEORGE WALLACE BAYNE
WILLIAM R. THURSTON

February 8, 1978

Mr. J. W. Decker 156 Riverview Dr. Durango, Colorado 81301

> Re : Kimbark Operating Co. #4A Horton Blanco MV well NW¼ Sec. 27, T32N, R12W San Juan County, New Mexico

Dear Mr. Decker:

We have requested permission from the USGS and BLM to drill a Mesa Verde gas well at the above location. We understand that you own the surface in the  $NW_3$  Sec. 27, T32N, R12W.

This location will be approximately 1300' southeast of the existing access road at the section corner. We plan to use existing roads in the area for access with a minimum of surface disturbance. The most dirt work will be the actual well-site location.

The BLM now requires a written plan of restoration to take place after cessation of operations. We suggest the following:

At the conclusion of drilling operations, the reserve dirt will be fenced, sheep tight, to allow pit to dry. After the reserve pit is covered, the location will be cleared and leveled. If the well is plugged and abandoned, any road will be restored, if requested, close to original condition. Disturbed areas will be reseeded, if required, as per surface owner's recommendation, or that of the BLM.

Mr. J. W. Decker Page 2

If the foregoing is satisfactory to you, we would appreciate your concurrence by your signature below and returning one copy to the address below. If you have any questions, please call me collect at the telephone number below. Thanking you in advance.

Yours very truly,

Elliott A. Riggs, Agen

Kimbark Operating Co.

P. 0. Box 711

Farmington, NM 87401

(505) 325-9881 office

(505) 325-8194 home

EAR:je Enclosure (map)

J. W. Decker

Date