NO. OF COPIES RECEIVED	\top	
DISTRIBUTION	_	T
SANTA FE	+	
FILE	+	_
U.S.G.S.	†	
LAND OFFICE	+-	
OPERATOR	+	 -
	í	1

DISTRIBUTION		Form C-103	
SANTA FE	Supersedes Old		
	- MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65	
U.S.G.S.			
LAND OFFICE		5a. Indicate Type of Lease	
OPERATOR		State X Fee XX	
		5. State Oil & Gas Lease No.	
(DO NOT USE THIS ESS)	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. CATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)		
USE "APPLI	PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DESCRIPTION FOR PERMIT - " (FORM CHOOSE)		
	COLOT) FOR SUCH PROPOSALS.)		
2. Name of Operator	OTHER.	7. Unit Agreement Name	
1			
TENNECO 3. Address of Operator	_	8. Farm or Lease Name	
3. Address of Operator		Cardon Com	
Box 3249 Englewood, Colorado 80155		9. Well No.	
4. Location of Well		#1	
UNIT LETTER A 1130 FEET FROM THE NORTH LINE AND 1050 FEET F		10. Field and Pool, or Wildcat	
	FEET FROM THE NOT LINE AND 1050 FEET F		
THE East	TION 27 TOWNSHIP 32N RANGE 13W NMP	Blanco Mesaverde/B.Dako	
	TIDN TOWNSHIP 3ZN RANGE 13W NMP		
	15. Elevation (Show whether DF, RT, GR, etc.)	**:\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
	5897'	12. County	
Check		San Juan	
NOTICE OF	Appropriate Box To Indicate Nature of Notice, Report or O	ot D	
NOTICE OF	INTENTION TO:	ther Data	
PERFORM REMEDIAL WORK		NT REPORT OF:	
TEMPORARILY ABANDON	PLUG AND ABANDON REMEDIAL WORK		
PULL OR ALTER CASING	COMMENCE DRILLING OPNS.	ALTERING CASING	
THE CASING	CHANGE PLANS CASING TEST AND CEMENT JOB X	PLUG AND ABANDONMENT	
OTHER	OTHER		
7. Describe Proposed or Completed O	perations (Clearly state all pertinent details, and give pertinent dates, including	_	
WORK) SEE RULE 1103.	positions (Crearry state all pertinent details, and give pertinent dates, including	e estimated day	
and 150 sx CT_P	(5113') of 7" csg. set @ 5099' W/DV @ 3621'	7mh 17/100	
by 150 sy CL-B noot	stage tool. Circ and WOC 4 hrs. Cmt 2nd stage	M/100 sx BJ Lite	
Drill 300' amb T	(5113') of 7" csg. set @ 5099' W/DV @ 3621'. (stage tool. Circ and WOC 4 hrs. Cmt 2nd stage Cmt. returned to surface. Drill DV tool @ 3460' to 1100 PSI for 15 mins. OK.	w/550 sx lite followed	
Test t	to 1100 PSI for 15 mins. OK.	. TIH to bottom.	
		The state of the s	
α			
I haray /			
I hereby certify that the information at	bow is true and complete to the best of my knowledge and belief.		
	A mowledge and belief.		
ED WILL M	Tilling Asst Div Adm		
1 100	Asst. Div. Adm. Mgr.	November 4, 1980	
		UATE	
Original Signed by FRANK	C T. CHAVEZ		
pr	SUPERVISOR DISTRICT # 3	NOV 71980	
DITIONS OF ARREST	TITLE	14(14 / Name)	

CONDITIONS OF APPROVAL, IF ANY: