

6 BLM
Form 3,60-5
(November 1983)
(Formerly 9-331)

1 Sun Gas Co. 1 Navajo Nation 1 File
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR

P O Box 208, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FNL - 1980' FWL

RECEIVED
JUL 15 1986
BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, ST, GR, etc.)

5434' GL; GL=RKB

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-586

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT/AGREEMENT NAME

8. FARM OR LEASE NAME

Hogan

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Horseshoe Gallup

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 32, T32N, R17W, NMPM

12. COUNTY OR PARISH

San Juan

13. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged and abandoned well as follows:

1. Spotted 10 sk (11.8 cf) cement plug 1074' to 942'.
2. Spotted 15 sx (17.7 cf) 198' to surface.
3. Removed casing & tubing heads.
4. Installed dry hole marker.
5. Left 9.0± mud between plugs.

This work was completed 7-11-86. Will remove equipment and restore location at later date.

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED

Jim L. Jacobs

TITLE

Geologist

DATE 7-14-86

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

JUL 18 1986

AREA MANAGER
FARMINGTON RESOURCE AREA

NMOCC
*See Instructions on Reverse Side