Form 9-331 a (Feb. 1951)				

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Office	ents Pe
Lease No	C78311
Unit	Candiff

	SUE	SEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLAN		SEQUENT REPORT OF SHOOTING OR ACIDIZING	1
NOTICE OF INTENTION TO TEST WATER S	SHUT-OFF	SEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR	REPAIR WELL SUE	SEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR AC	IDIZE SUE	SEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTE	R CASING SUF	PLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WEL	.L		
(INDICATE A	BOVE BY CHECK MARK NATURE (OF REPORT, NOTICE, OR OTHER DATA)	
		June 21.	. 195
	()	ine and \mathcal{L} ft. from \mathcal{L} line of se	ec19_
(½ Sec. 19	(Twp.) (Range)	(Meridian)	
(Field)	(County or Subdivis	ion) (State or Territory)	
he elevation of the derrick flo	oor above sea level is	5906 ft.	
	DETAILS OF	WORK	
	ing points, and all other impo	s, and lengths of proposed casings; indicate mudding trant proposed work)	g jobs, ceme
On 6-15-57, Potal Dept Ren 105 joints 7-5/8". Two stage commuting to coment, 50 sacks Power followed with 50 sacks coment, 75 sacks Power 1000# 30 minutes.	ing points, and all other imports. th 4300'. , 25.40\$, J-55 cas. col at 2152'. Firstly gel and s Heat Cament. Se ix with 45 gel and	ing (4987') set at 4297'. t stage 50 sacks Regular 1/4 Flucals per saks, cond stage 75 sacks Regular 1/4 Flucals per saks. Belo	PLA On
On 6-15-57, Potal Dept Ren 105 joints 7-5/8". Two stage commuting to coment, 50 sacks Possis followed with 50 sacks coment, 75 sacks Possis 1000# 30 minutes. Top of coment by temps	ing points, and all other imports. th 4300'. 26.40\$, J~55 cas. col at 2152'. Firstly with 45 gel and sheat Cament. Selix with 45 gel and brature survey on	ing (4967') set at 4297'. t stage 50 sacks Regular 1/44 Flocals per sakk, cond stage 75 sacks Regular 1/44 Flocals per sack. Held	REL.
On 6-15-57, Potal Dept Ren 105 joints 7-5/8" Two stage commuting to coment, 50 sacks Possit followed with 50 sacks coment, 75 sacks Possit 1000# 30 minutes. Top of coment by temporary of coment by temporary for the company of coment by temporary of com	ing points, and all other imports. th 4300'. 26.40\$, J~55 cas. col at 2152'. Firstly with 45 gel and sheat Cament. Selix with 45 gel and brature survey on	ing (4967') set at 4297'. t stage 50 sacks Regular 1/44 Flocals per sakk, cond stage 75 sacks Regular 1/44 Flocals per sack. Held second stage at 1535'.	REL.
On 6-15-57, Potal Dept Ran 105 joints 7-5/8" Two stage commuting to coment, 50 sacks Posser followed with 50 sacks coment, 75 sacks Posser 1000# 30 minutes. Top of coment by temporal understand that this plan of work me	ing points, and all other imports. th 4300'. , 25.40\$, J~55 cas. Gol at 2152'. Firstly with 45 gel and s Heat Cament. See ix with 45 gel and brature survey on a	ing (4967') set at 4297'. t stage 50 sacks Regular 1/44 Flocals per sakk, cond stage 75 sacks Regular 1/44 Flocals per sack. Held second stage at 1535'.	PLI On,