Form 3160-5 (June 1990)

S

Conditions of approval, if any:

representations as to any matter within its jurisdiction.

UNITED STATES

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

	DEPARTMENT OF THE INTENION
	BUREAU OF LAND MANAGEMENT
5. Leas	INDRY NOTICES AND REPORTS ON WELLS
	MARK MOTICES AND REPORTS ON MELLS

se Designation and Serial No. SF-078147 6/If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation 8, Well Name and No. MOORE LS #5 9. API Well No. 3004560070 10. Field and Pool, or Exploratory Area **BLANCO MV** 11, County or Parish, State **SAN JUAN NEW MEXICO** Change of Plans **New Construction** Non-Routine Fracturing

Use "APPLICATION FOR PERMIT - " for such proposals 1. Type of Well Oil Well X Gas 2. Name of Operator AMOCO PRODUCTION COMPANY **DALLAS KALAHAR** 3. Address and Telephone No. (303) 830-5129 P.O. Box 800, Denver, Colorado 80201 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec. 24 T 32N R 12W 990 FSL 1650FWL CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Abandonment Notice of Intent Recompletion Plugging Back Subsequent Report Casing Repair Altering Casin Other REPAIR - SET LINER Final Abandonment Notice (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work . If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) SEE ATTACHED FOR PROCEDURES. OIL COM. DIV. IF YOU HAVE ANY QUESTIONS CONTACT DALLAS KALAHAR AT (303)830-5129. 03-07-1994 (This space for Federal or State office use) APPROVED Approved by

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States and last terminal property of t

GENERAL INSTRUCTIONS

This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning

the use of this form and the number of copies to be submitted, particularly with regard to local area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

SPECIFIC INSTRUCTIONS

Item 4 - If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 13 - Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones,

or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

NOTICE

The Privacy Act of 1974 and the regulation in 43 CFR 2.48(d) provide that you be furnished the following information in connection with information required by this application.

AUTHORITY: 30 U.S.C. 181 et. seq., 351 et. seq., 25 U.S.C. et. seq.; 43 CFR 3160.

PRINCIPAL PURPOSE - The information is to be used to evaluate, when appropriate, approve applications, and report completion of secondary well operations, on a Federal or Indian lease.

ROUTINE USES:

- (1) Evaluate the equipment and procedures used during the proposed or completed subsequent well operations.
- (2) Request and grant approval to perform those actions covered by 43 CFR 3162.3-2(2)
- (3) Analyze future applications to drill or modify operations in light of data obtained and methods used.
- (4)(5) Information from the record and/or the record will be transferred to appropriate. Federal, State, local or foreign agencies, when relevant to civil, criminal, or regulatory investigations or prosecutions.

EFFECT OF NOT PROVIDING. INFORMATION - Filing of this notice and report and disclosure of the information is mandatory once an oil or gas well is drilled.

The Paperwork Reduction Act of 1980 (44 U.S.C. 3501, et. seq.) requires us to inform you that:

This information is being collected in order to evaluate proposed and/or completed subsequent well operations on Federal or Indian oil and gas leases.

This information will be used to report subsequent operations once work is completed and when requested, to obtain approval for subsequent operations not previously authorized.

Response to this request is mandatory for the specific types of activities specified in 43 CFR Part 3160.

BURDEN HOURS STATEMENT

Public reporting burden for this form is estimated to average 25 minutes per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to U.S. Department of the Interior, Bureau of Land Management, (Alternate) Bureau Clearance Officer, (WO-771), 18 and C Streets, N.W., Wasington, D.C. 20240, and the Office of Management and Budget, Paperwork Reduction Project (1004-0135), Washington, D.C. 20503.

REPAIR PROCEDURE MOORE LS 5 MV

March 3, 1994 (Original version)

- 1. Record TP, SICP, and SIBHP.
- 2. MIRUSU.
- 3. TOH with 2 3/8" tubing.
- 4. Clean out well to TD (5589').
- 5. TIH with a 3 1/2", flush joint liner, set liner hanger between 5190' and 5220'; land liner at 5589'.
- 6. Cement liner into place. WOC.
- 7. Drill out cement to 5580'.
- 8. Pressure test easing and liner tops to 3500 psi.
- 9. Run a GR correlation log from 5580' to 4645' and match up with Schlumberger's Electric, Gamma Ray, Induction Log dated 55/02/28. Also correlate the Moore LS 7A Compensated Density Log dated 78/06/14. Before continuing, rush a copy of the correlation log to Paul Edwards in Denver so he can verify that the intervals in step 10 and 13 are correct.
- 10. RU lubricator and perforate the Point Lookout with a x x/x" casing gun, 2 JSPF, 120 degree phasing, and xx g charges. Depths are based on Schlumberger's Electric Log, so be sure to adjust these depths according to the correlation log before perforating. Charges for the perforations from 5252' through 5279' should give maximum penetration due to the presence of two strings of pipe.

POINT LOOKOUT PERFORATIONS

- 11. Fracture stimulate according to the attached Point Lookout frac schedule.
- 12. TIH with a RBP and set in the 5 1/2" liner at 5180'. Cap with sand.
- 13. RU lubricator and perforate the Cliffhouse with a 4" casing gun, 2 JSPF, 120 degree phasing, and 23 g charges. Depths are based on Schlumberger's Electric Log, so be sure to adjust these depths according to the correlation log before perforating.

CLIFFHOUSE PERFORATIONS

4748' - 57'	4761' - 64'	4772' - 75'	4855' - 64'	The March 2 1284
4868' - 72'	4877' - 88'	4893' - 98'	4906' - 14'	• • •
		4936' - 38' 5134' - 37'	4944' - 46' 5162' - 64'	ONL COME DAY
4988 - 97	3070 - 19	3134 - 37	3102 - 04	19167°, A

- 14. Fracture stimulate according to the attached Cliffhouse frac schedule.
- 15. TIH with a RBP and set at 4600'.
- 16. Run a GR/CBL from the RBP to surface. Determine TOC.
- 17. Perforate 2 squeeze holes within 100' of the TOC.
- 18. Conduct cement squeezes and run CBLs until cement is to surface and casing will hold a 500 psi pressure test.
- 19. Drill out cement and clean out well to RBP at 4600'.
- 20. TOH with RBPs and clean out to PBTD with N2 and small tubing.
- 21. Swab/flow back load.
- 22. Once sand entry has ceased, land either 1 1/2" or 2" coiled tubing at 5400' with a seating nipple 30' off bottom. Tubing sized will be determined based on the flow back response.
- 23. Tie well back into surface equipment and return to production.

The second secon		
and the second s		
ger of the control o		
in the control of the		
and the second of the second o		