

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well <input type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <u>Water Source</u>	5. Lease Designation and Serial No. <u>14-20-600-3540</u>
2. Name of Operator <u>APA Development Corp ICO NM000</u>	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. <u>1000 Rio Brazos Aztec NM 87410</u>	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) <u>Sec 35 32N 17W</u> <u>Unit Letter D 650' FNL 640 FWL</u>	8. Well Name and No. <u>Navajo P-14</u>
	9. API Well No. <u>30-045-87060</u>
	10. Field and Pool, or Exploratory Area <u>WTR Supply</u>
	11. County or Parish, State <u>Santa Juan</u>

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attachment

BUREAU OF LAND MANAGEMENT
WASHINGTON FIELD OFFICE

FOR RECOR

04 2002

FIELD OFFICE

14. I hereby certify that the foregoing is true and correct.

Signed

Randy Blackburn

Title

P&A Supervisor

Date

3-24-02

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

**KEY ENERGY SERVICES
P&A OPERATION
CEMENT SERVICE REPORT**

WELL NAME: NAVAJO P-14

TOTAL PLUGS: 5

DATE STARTED: 12-10-01

TOTAL SACKS: 356

DATE COMPLETED: 12-17-01

WITNESS: HENRY VILLENUEVA

MOL. ND WELL HEAD & NU BOP AND TEST. WORK STUCK TUBING. POOH W/RETA PUMP. TIH TO 2601'.

PLUG #1: 2601'-2414'. 36 SX. WOC. NO TAG. RECEMENT W/36 SX. TAG @ 2586. PRESSURE TEST TO 500 PSI. GOOD. SPOT 30 SX @ 2586'.

PLUG #2: 2312'-2146'. 32 SX. LD TUBING TO 1498'.

PLUG #3: 1498'-1332'. 32 SX. POOH. PERF @ 370'.

PLUG #4: 370'-220'. 97 SX. (67 SX OUTSIDE & 30 SX INSIDE). TAG @ 236'. PERF @ 145'.

PLUG #5: 145'-SURFACE. 93 SX.

ND BOP & DIG CELLAR. CUT OFF WELL HEAD. INSTALL DRY HOLE MARKER.

A handwritten signature in black ink, reading "Randy Blackmon", with a long horizontal flourish extending to the right.

RANDY BLACKMON
P&A SUPERVISOR