	-				Form C-103
DISTRIBUTION					Supersedes Old
ANTA FE		N	EW MEXICO OIL CONS	ERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
LE	• 🗆 🛶				
s.g.s.					5a. Indicate Type of Lease
ND OFFICE					State Fee. X
ERATOR	-				5. State Oil & Gas Lease No.
(DO NOT USE THIS FOR USE	SUNDRY	NOTICES	AND REPORTS ON L OR TO DEEPEN OR PLUG E -" (FORM C-101) FOR SUC	WELLS ACK TO A DIFFERENT RESERVOIR.	
OIL GAS WELL		OTHER-	·		7. Unit Agreement Name
ame of Operator  C.S.T. ENTER	PRISES	TNC.			8, Farm or Lease Name Morfine
Address of Operator		, 2	<del></del>		9. Well No.
Box 1200 Far	mingto	n. New	Mexico 8740	1	1
ocation of Well					10. Field and Pool, or Wildcat
UNIT LETTER K	21	195 FEE	T FROM THE South	LINE AND 1960 FEET	FROM
	· · · · · · · · · · · · · · · · · · ·	_			
THE WOST LI	INE, SECTIO	. 6	TOWNSHIP 22 N	RANGE 3 E	NMPM. (())
	//////	15.	Elevation (Show whether	DF, RT, GR, etc.)	12, County
			<b>6890</b> ° GR		Rio Arriba
		ppropriate TENTION		Nature of Notice, Report o	or Other Data UENT REPORT OF:
<del>[</del>	1			_	,
FORM REMEDIAL WORK	] ]		PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
PORAFILY ABANDON	<u> </u> 		(Title)	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
			, <del>-</del>	1	7
L OR ALTER CASING			CHANGE PLANS	CASING TEST AND CEMENT JOB	
Describe Proposed or Conwork) SEE RULE 1103. In to drill 9' Burface, the	npleted Ope holen dril	to 10	rly state all pertinent deto  0° - set & ce  1 to the Penn	other other ails, and give pertinent dates, incoment 7" surface of sand with 64"	
Describe Proposed or Conwork) SEE RULE 1103. In to drill 9' surface, their	npleted Ope hole n dril Compl	to 10. l ahea.	rly state all pertinent deto  0' - set & ce  d to the Penn  Ll and set pu	otherails, and give pertinent dates, incoment 7" surface	casing circulated oit. Test same
Describe Proposed or Con work) SEE RULE 1103. An to drill 9' surface, then productive.	npleted Ope hole n dril Compl	to 10. l ahea.	rly state all pertinent deto  0' - set & ce  d to the Penn  Ll and set pu	other	casing circulated oit. Test same
Describe Proposed or Conwork) SEE RULE 1103. In to drill 9' surface, their	npleted Ope hole n dril Compl	to 10. l ahea.	rly state all pertinent deto  0' - set & ce  d to the Penn  Ll and set pu	other	casing circulated oit. Test same
Describe Proposed or Con work) SEE RULE 1103. An to drill 9' surface, then productive.	npleted Ope hole n dril Compl	to 10. l ahea.	rly state all pertinent deto  0' - set & ce  d to the Penn  Ll and set pu	other	casing circulated oit. Test same
Describe Proposed or Con work) SEE RULE 1103. An to drill 9' surface, then productive.	npleted Ope hole n dril Compl	to 10. l ahea.	rly state all pertinent deto  0' - set & ce  d to the Penn  Ll and set pu	other	casing circulated oit. Test same
Describe Proposed or Con work) SEE RULE 1103. An to drill 9' surface, their productive.	npleted Ope hole n dril Compl	to 10. l ahea.	rly state all pertinent deto  0' - set & ce  d to the Penn  Ll and set pu	other	casing circulated oit. Test same ter.
Describe Proposed or Conwork) SEE RULE 1103. In to drill 9' surface, their productive.	npleted Ope hole n dril Compl	to 10. l ahea.	rly state all pertinent deto  0' - set & ce  d to the Penn  Ll and set pu	other	casing circulated oit. Test same
Describe Proposed or Conwork) SEE RULE 1103. In to drill 9' surface, their	npleted Ope hole n dril Compl	to 10. l ahea.	rly state all pertinent deto  0' - set & ce  d to the Penn  Ll and set pu	other	casing circulated oit. Test same ter.
Describe Proposed or Conwork) SEE RULE (103. In to drill 9 surface, their productive.	npleted Ope hole n dril Compl	to 10. l ahea.	rly state all pertinent deto  0' - set & ce  d to the Penn  Ll and set pu	other	casing circulated oit. Test same ter.
Describe Proposed or Conwork) SEE RULE (103. In to drill 9 surface, their productive.	npleted Ope hole n dril Compl	to 10. l ahea.	rly state all pertinent deto  0' - set & ce  d to the Penn  Ll and set pu	other	casing circulated oit. Test same ter.
Describe Proposed or Con work) SEE RULE (103. In to drill 9' surface, then productive.	npleted Ope hole n dril Compl	to 10. l ahea.	rly state all pertinent deto  0' - set & ce  d to the Penn  Ll and set pu	other	casing circulated oit. Test same ter.
Describe Proposed or Con work) SEE RULE (103. In to drill 9' surface, then productive.	npleted Ope hole n dril Compl	to 10. l ahea.	rly state all pertinent deto  0' - set & ce  d to the Penn  Ll and set pu	other	casing circulated oit. Test same ter.
Describe Proposed or Conwork) SEE RULE 1103. In to drill 9' surface, their productive. In to use 7"	npleted Ope n dril Compl	to 10 1 ahea ete we:	rly state all pertinent det.  O' - set & ce  d to the Penn  Ll and set pu  ,000 lb. test	other	casing circulated oit. Test same ter.
Describe Proposed or Conwork) SEE RULE 1103. In to drill 9' surface, then productive. In to use 7"	npleted Ope n dril Compl	to 10 1 ahea ete we:	rly state all pertinent det.  O' - set & ce  d to the Penn  Ll and set pu  ,000 lb. test	other ails, and give pertinent dates, incoment 7" surface of sand with 64" to be apping equipment.  To finy knowledge and belief.	asing circulated oit. Test same ter.
Describe Proposed or Conwork) SEE RULE 1103. An to drill 9's surface, then productive. An to use 7"	npleted Ope n dril Compl	to 10 1 ahea ete we:	rly state all pertinent det.  O' - set & ce  d to the Penn  Ll and set pu  ,000 lb. test	other ails, and give pertinent dates, incoment 7" surface (a. sand with 64") amping equipment.  blow out prevent	asing circulated oit. Test same ter.
Describe Proposed or Comwork) SEE RULE 1103.  an to drill 9' surface, then productive. an to use 7"	npleted Ope n dril Compl	to 10 1 ahea ete we:	rly state all pertinent det.  O' - set & ce  d to the Penn  Ll and set pu  , 000 lb. test	other ails, and give pertinent dates, incoment 7" surface of sand with 64" to be apping equipment.  To finy knowledge and belief.	AUG 16 1976
Describe Proposed or Conwork) SEE RULE 1103.  Rn to drill 9' Surface, then productive.  Rn to use 7"  I hereby certify that the in	hole hole completed Ope hole n dril Completingle	erations (Clean to 10)  I ahea  ete we  ram 3	and complete to the best of the period to the best of the period to the best of the period to the best of the period to the peri	other ails, and give pertinent dates, incoment 7" surface (a. sand with 64") amping equipment. blow out prevent	AUG 16 1976  AUG 16 1976  DATE 8-16-76
Describe Proposed or Conwork) SEE RULE 1103.  An to drill 9' Surface, their productive.  An to use 7"  I hereby certify that the in the productive of the productive of the productive.  ROVED BY ARCONDITIONS OF APPROVAL  MOUNTAINS OF APPROVAL	hole hole completed Ope hole n dril Completingle	to 100.1 ahea. ete wei ram 3	and complete to the best of the period to the best of the period to the best of the period to the best of the period to the peri	other ails, and give pertinent dates, incoment 7" surface (a. sand with 64") amping equipment. blow out prevent	AUG 16 1976  AUG 16 1976  DATE 8-16-76