

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name <b>Santa Fe</b>
9. Well No. <b>2</b>
10. Field and Pool, or Wildcat <b>Wildcat</b>
12. County <b>McKinley</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dryhole</b>
2. Name of Operator <b>Walker Bros. Oil Company</b>
3. Address of Operator <b>P. O. Box 18715, Oklahoma City, Okla.</b>
4. Location of Well UNIT LETTER <b>A</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>N East</b> LINE, SECTION <b>7</b> TOWNSHIP <b>17N</b> RANGE <b>8W</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>6908 KB</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Plugged #2 Santa Fe as follows on May 18, 1965**  
**100' plug - 20 sx, 1612-1512**  
**50' plug - 10 sx -m 400-450'**  
**40' plug - 8 sx - 90-130'**  
**10' plug at top with 4' iron marker in top.**  
**Cleaned up location and leveled pits.**



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *R. E. Larch* TITLE **Geologist** DATE **May 18, 1965**

Original Signed Emery C. Arnold

APPROVED BY *Emery C. Arnold* TITLE **Geologist**

DATE **JUN 8 1965**

CONDITIONS OF APPROVAL, IF ANY: