

FEDERAL SURFACE

Attachment to Notice of
Intention to Abandon

U. S. GEOLOGICAL SURVEY
P. O. Box 959
Farmington, New Mexico 87401

3-19-81

Re: Permanent Abandonment

Well: # 24(A-9) Puerto Chiquito

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases".
2. The Farmington office (telephone (505) 325-4572) is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. We have asked the Bureau of Land Management for the surface restoration requirements for this well and we should be able to furnish you these requirements within 30 days. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
5. The surface management agency is to be notified when surface rehabilitation is complete.
6. The following modifications to your plugging program are to be made (when applicable):
 - a) Perforate 3½" tubing at 299' and place cement plug inside and outside tubing to 199'.
 - b) Place 10' cement plug inside tubing at surface.

Office Hours: 8:00 A.M. to 5:00 P.M.
Farmington Personnel to be notified:

Home Telephones:

Ray Swanson: Petroleum Engineering Technician - 325-8189
Fred Edwards: Petroleum Engineering Technician - 325-7885
Ken Baker: Petroleum Engineering Technician - 327-2170